Examination[Remington/CF/BA]

Part

Sub-Part

Remington Arms Co., Inc.
Product Service
Legal Case #:9046

Case Information Pre Lit Lit Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** 315248 7/10/2013 7/18/2013 7/18/2013 Customer Information Last Type Business Street City State Zip Age Contact Name Name H 727-865-8571 4985 60th Saint Incident Bruce Wakeman FL 33715 E Ave. South Petersburg lastpassagrille@gmail.com Incident Information Codes Repair Est. Medical Treatment Medical Status Claims ΡI PD Cause:4006 Altered Adjustments or Components Unknown FBC Concern:1008 Fired on Bolt Closing S C Per service request - Has had several discharges while closing bolt and while taking safety off. jbi Firearm Information **DOM** Model/Ga. SKU Serial Bbl. Mfg. Type CF/BA 7/223 REM 29539 7801360 CY 4/26/2004 3:04:57 PM Remington **Date Purchased** Where Purchased Accessories Original Owner HICKS INC U CONCERN:FBC, FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/7/CF/BA Reim. Cash Reimbursement Settlement Cash Settlement Release of Claims Release Date Date Date Offer to replace trigger assembly, clean, and test at 50% discount Repair/Replacement Repair/Replacement 7/19/13: Per Ilion, could not duplicate concern / trigger assembly set screws altered / replace trigger assembly clean & test for 50% normal cost, jbi 7/22/13: Customer called in to Consumer Service Dept and approved with credit card. jbi

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9046&Type=... 7/22/2013

Comment

Code

PrintDisplay Page 2 of 3

	Examiner		B.TRAVIS
Examination	Exam Date		7/18/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description		20" 223 REM
Barrel	Date Code		CY
	Bore Plugged	False	
	Bulged	False	7
	Fired	False	7
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	7
	Shroud	Slightly Worn; Functioning	<u> </u>
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	7
	Ext/Eject Test	False	7
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	7
	Notch Condition	Select	Ħ
	Exterior Condition	Slightly Worn; Functioning	7
Overall	Stock Condition	Slightly Worn; Functioning	RECOIL PAD IS STICKY, COMING APART
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	7
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	EXCESSIVE OVER TRAVEL
	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED
			1

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9046&Type=... 7/22/2013

Sub-Assembly

Other Remington

Quotation

Remington Service

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00315248		Serial Number / Description 7801360 Model 7 Center Fire Caliber: 223 REM					e Date:	07/10/2 07/18/2 07/19/2	013			
Customer: BRUCE WAKEMAN 4985 60TH AVE SOUTH SAINT PETERBURG, FL 33715 US				Return To: BRUCE WAKEMAN 4985 60TH AVE SOUTH SAINT PETERBURG, FL 33715 US								
Please Circle One VISA MC Open Accoun		/ER Card NoPO Numb	er:	Exp.Date								
Daytime Phone	e: ()ge, please use the reverse side for your	_ Time to C comments ar	to Call:								
Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M295 - EVALUATE AND REPAIR/SAFETY INSP. M295 - EVALUATE AND REPAIR/SAFETY INSP.												
could not dupliua	te concern	/ trigger assembly set scres altered / re	echnician C place trigger		ean & test for 509	% normal c	ost	-				
Material	Туре	ESTIMATE (note: C.O.D./Shipping Description	and Handli	ng Charges Qty Needed	are NOT Include Warranty	ed in this Q Qty From Inv		Disc	Amount			
F305574B 4000118 4000119	Part Service Service	7 X-MARK PRO TRIG ASSB - GR-CLEAN GR-TEST	BLACK (O	OS) 1 1 1	Billable Billable Billable	1 1 1	97.00 28.00 23.00	50	48.50 14.00 11.50			
						Est	Total: Sales Tax:		74.00 4.44			
						Gra	and Total:		\$78.44			

Service Request

Remington Service

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

Model SEVEN RIFLE Caliber: 223

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCI YOUR RETURN.

Date of Request 96/24/2013 Printed36/24/2013

Destination: Arms Services 14 Hoefler Ave Lion, NY 13357 US

Email: lastpassagrille@gmail.com

SAINT PETERBURG, FL 33715 US

Customer: BRUCE WAKEMAN 4985 60TH AVE SOUTH

SR00055627

Service Request Numberrial Number / Description

7801360

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep returned. If not, you will be contacted with an estimate before work is performed.

Service Request Section.

Has several discharges while closing bolt and while taking safety off perform all safety inspections and repair as needed

Parts And Service Details William Qty Warranty Price Disc Amount Needed

3601360

Model:

Sub Total: Est Sales Tax:

.00 .00

Could Not duplimate LONCERN
T. A. Set Screws Altered
Replace T. A. Clean retest Rine
At 1/2 Normal Cost.









