

Remington Arms Co., Inc.
Product Service
Legal Case #:9564

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		11/26/2013		11/22/2013			X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Hubert	Mitchell	1856 Morey Rd	Fredericktown	PA	15333		H 724-809-1992

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4079 Other - Unexamined			Unknown
S FBC and FSR	Concern:1008 Fired on Bolt Closing			
C				

11/26/13: I received call from Hubert Mitchell, he said that he went bear hunting and was checking to make sure it was sighted in before heading out. He said that the gun fired on bolt closing and also on fired on safety release. No injury. jbi

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	710/3006 SPR	27410	71068992		7/15/2002 10:44:33 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART DC 6003R- REGULAR		N			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

12/1/13: Sending ARS, letter, and SR paperwork. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment

ARS LABEL REQUEST FORM

DATE: 12/01/2013	Service Request # SR00009270
QUANTITY: 1	WEIGHT PER PACKAGE: 10 LBS
REQUESTED BY: [redacted]	email address: [redacted]

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	HUBERT MITCHELL 1856 MOFFLY RD FREDERICKTOWN, PA 17033 US SR00009270 Email:
RETURN ITEM TO:	ILN Arms Services



201306 DEC 2, 2013 ALL CORR USD 2 SF 1
 SVC ENDCON RCT UT 10 0 LBS
 TRACKING# 124X12000001000473
 REF 1: SR00009270
 REF 2:

HANDLING CHARGE 0.00		
SINGLE-PIECE PUB RATE CHRG:		
SV 0.00	CD 0.00	RS 0.00
OC 0.00	DD 0.00	SD 0.00
OH 0.00	PR 0.00	SP 0.00
TOT PUB CHG 10.34	PUB-HANDLING 10.34	

ATTN: Product Service