Obsolete

Remington Arms Co., Inc. Product Service Legal Case #:8688

Case Information Date Opened(PS) **Date Closed** Incident Date RE# **Date Opened** 3/8/2013 3/27/2013 305661 3/22/2013

Customer Information

Lit

Last Name Street City Zip Contact Business First Name Type State Age C 413-579-2651 110 Willow Incident Daniel Novitski Plymouth PA 18651 E dnovitski6@yahoo.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

Pre Lit

ΡI

PD

Cause: 4038 Could Not Duplicate Concern

S Fired when closing bolt

Concern:1008 Fired on Bolt Closing

Unknown

3/8/13 Per email from Loschin/Zook, a friend of Zook had a problem with a 710 rifle. Last year while sighting in the rifle for deer season, a cartridge was placed in the chamber, when he closed the bolt, the gun fired. I would like to have the firearm checked out, serviced, etc. to make sure it is operating safely.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

710/270 WIN

27408

71058988 CW 4/26/2002 3:02:05 PM

Date Purchased

Where Purchased

Accessories

Original Owner

WAL-MART DC 6003R-REGULAR SCOPE BASE, SLING

U

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Date APV

Reim.

Cash Date APV

Check over, repair, adjust, clean and test as needed at no charge

Repair/Replacement

Repair/Replacement

Cost

Date

3/27/2013 27.00

3/8/13 Called Daniel and offered to send prepaid shipping label to have it come for inspection. He agreed.cm 3/27/13 Will check over, repair, adjust, clean as needed at no charge as goodwill gesture. Will function check and test fire with a slave magazine.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/25/2013
	Product Type		RF
	Action Type]	Α ·
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	OLD STYLE TRIGGER ASSEMBLY NO LONGER AVAILABLE FOR REPAIR
	Description		22" 270 WIN
	Date Code		CW
	Bore Plugged	False	
			7.

PrintDisplay Page 2 of 2

1	Bulged	False	
Barrel	Fired	False]
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt ·	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Missing	
	Exterior Condition	Slightly Wom; Functioning	ACTION UNDER STOCK RUSTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	<u> </u>
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
P. 1. (P. :	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	Select	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SLING

Remington.

4.5# CW4/07

March 8, 2013

86.88

Daniel Novitski 110 Willow Plymouth, PA 18651

Subject: Case #8688, Model 710, SR# 47359

Dear Mr. Novitski,

Please include a copy of this letter with the firearm as well as the Service Request form. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the product is logged in correctly. Please mark the small ends of the boxes "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

enclosure

71058988 Model: 710 RE00305661 could not sup concerns
T.A. + Aul. dirky + rusty

PECEIVE 1 PAR 2 6 2013

BY:....

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

ervice Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Prod Serv #8688

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00047359	Serial Number / Description 71058988		Date of Request: Date Printed:	03/08/2013 03/08/2013
Customer: DANIEL NOVITSKI 110 WILLOW	Model 710 RIFLE Caliber: 270	Destination: Arms Services 14 Hoefler Ave		
PLYMOUTH, PA 186	51 US	Ilion, NY 1335	7 US	
Email:		Email:		•
Your request for service on the returned. If not, you will be co	e item(s) will be evaluated by our repairman to do intacted with an estimate before work is perform	stermine if it is covered under our warranty ped.	oolicy. If it is your firearm	will be repaired and
Reason For Return M123 - FORWARD TO	PRODUCT SERVICE FOR INSPECTION			
Service Request Section Prod Serv #8688				
Parts And Service Details Material Type	Description	Qty Warranty Needed	Price	Disc Amount
	•			
THIS IS NOT AN INVOICE. T being sent based on the conven	This is a pre-estimate to repair, recondition, or repair, with our representative.	place the item(s)	Sub Total: Est Sales Tax:	.00
			Grand Total:	\$.00

Mitchell, Christy

From:

Loschin, John

Sent:

Friday, March 08, 2013 10:10 AM

To: Subject: Mitchell, Christy FW: firearm service

Please assist

From: Zook, Robert R.

Sent: Friday, March 08, 2013 9:58 AM

To: Loschin, John **Cc:** Novitski, Daniel J **Subject:** firearm service

John,

Last week, when we were on the phone, I mentioned that a buddy of mine has rifle that fired when he closed the bolt. Here is the information.

8688

Model 710 Caliber: 270 win Serial #: 71058988

Issue: while sighting in the rifle, a cartridge was placed in the chamber, when he closed the bolt, the gun fired

I would like to have the firearm checked out, serviced, etc.. to make sure it is operating safely! If there are any charges, please let me know.

This is a long-time family friend of mine and want to make sure all is well.

Home address: Daniel Novitski 110 Willow Plymouth, PA 18651 (413) 579-2651 – cell phone

Please let me know if you need more information. I have copied Dan on this email in case you need an email address. Thank you,

Zook

ARS LABEL REQUEST FORM

DATE:	03/08/2013	Service Request #	SR00047359	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	mitchelles	email address:	Christy.Mitchell@remington.com	

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.remington.com

LABEL INFORMATION

MAIL LABEL TO:

DANIEL NOVITSKI 110 WILLOW

PLYMOUTH, PA 18651 US

SR00047359

Email:

RETURN ITEM TO:

ILN

Arms Services

4XX596 MAR 8, 2013 ALL CURR USD SVC GNDCOM TRACKING# 1Z4XX5969065206598 REF 1:SR00047359 1 OF 1 REF 2: SVC T/P USD RS 0.50 SD 0.00 SP 0.00 HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: 0.00

COD DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 9.04 0.00 9.04 0.00 PR PUB+HANDLING

ATTN: Prod Serv #8688







