PrintDisplay Page 1 of 3

> Remington Arms Co., Inc. **Product Service** Legal Case #:9273

Case Information

Date Opened(PS) Pre Lit Lit Obsolete RE# **Date Opened Date Closed Incident Date**

323345 10/7/2013 10/8/2013 10/8/2013

Customer Information

First Last City State Zip Age Type Business Street Contact Name Name

H 713-667-3281

Incident

4922 Beech Stafford Rusty

E

Bellaire TX 77401 St

staffordservices@yahoo.com

Incident Information

Repair Medical Medical Claims Codes Est. **Treatment** Status

ΡI

Could Not Duplicate PD Cause:4038

Concern Unknown

Unexplained Discharge - No S Mention of Safety Postion

Unexplained Discharge - No Concern:1025 Mention of Safety Position

C

Per SR00063042 Service Request Section, "Consumer stated that the firearm went off without touching the trigger." jbi

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

710/270 WIN

27408

71104997 AX 3/11/2003 10:45:21 AM

Date Purchased Where Purchased Accessories **Original Owner**

ACADEMY CORP

U

CONCERN: FIRED WITHOUT TOUCHING TRIG

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/710/CF/BA

Reim. Cash Cash Release of Claims Settlement Release Date Reimbursement Date Date Settlement APV

Remove and clean trigger assembly, function check and test fire at 50% discount.

> Repair/Replacement Repair/Replacement Cost Date

> > \$8

10/10/13: Per Ilion, "could not duplicate concern. Trigger assembly and action dirty, sticky and rusty. Check over completely. Remove and clean trigger assembly, function check and test fire at 1/2 normal cost. Repair recoil pad." jbi 10/11/13: I called customer with quote. He approved with credit card. jbi

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9273&Type... 10/11/2013

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		10/8/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		AX
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	1
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	1
	Shroud	Slightly Worn; Functioning]
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	1
Locking	Lug Condition	Slightly Worn; Functioning	
Locking	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Worn; Functioning	VERY DIRTY INSIDE AND OUT
Overall	Stock Condition	Worn; Functioning	DIRTY. RECOIL PAD BROKEN
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False	
G G	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	1
	Condition	Slightly Worn; Functioning	VERT DIRTY
			, , , , , , , , , , , , , , , , , , , ,

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9273&Type... 10/11/2013

Trigger	Pull	Select	5#	
	Altered	False	SEALANT PRESANT	
	Sub-Assembly	Other Remington		

Quotation

Remington Service PO Box 700

Estimating Report Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00323345	•				Date Re Estimat		10/07/2 10/08/2		
	M	fodel 710 Center Fire Caliber: 270 WIN			Date Pr	inted:	10/11/2	013	
Customer:			Retu	rn To:					
RUSTY STAFFORD				RUSTY STAFFORD					
4922 BEECH BELLAIRE, 7		TIC .		4922 BEECH ST BELLAIRE, TX		\$			
DELLAIRE,	IX //401 (03		DELLAIRE, TA	. 77401 0.	3			
Please Circle One:	:								_
VISA MC	DISCOVE	R Card No PO Number:		Exp	.Date				
Open Account	: R	PO Number:							
Annroval Signatur	re·				Date:				
Daytime Phone	e: ()	Time to Cal	l:						
		, please use the reverse side for your comments and							
		Problems							
Reported M123 - FORWA	ARD TO PR	Foundation ODUCT SERVICE FOR INSPECTION Mile		WARD TO PRO	DUCT SER	VICE FOR	INSPE	CTION	
101125	uco 10110	obdor sakvies i ok mor serion	-5 .01	WILL TO THE	DOCT ODA	· ICE I OIC	11101 11	CHOIL	
		Technician Con	iments						
		igger assembly and action dirty, sticky and rusty.ch	eck over co	mpletely.remove	and clean	trigger asse	mbly,fu	nction chec	k
and test fire at 1/2		t. repair recoil pad.	<u> </u>	NOS V I V					
Material	Type	STIMATE (note: C.O.D./Shipping and Handling Description	Charges a Qty	re NOT Include Warranty	ed in this Q Oty		Disc	Amount	
	.,,,,	•	Needed		From Inv	11100	2.50	/ Limount	
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)		Billable	1	17.00	0	17.00	
4000118 4000119	Service Service	GR-CLEAN GR-TEST	1 1	Billable Billable	1 1	28.00 23.00		14.00 11.50	
4000244	Service	GR-PARTS USED IN REPAIRS (MISC)	20	Billable	20	1.00		10.00	
		•							
						b Total: : Sales Tax:		52.50 3.54	
					£St	Sales 1 ax:		3.54	
					Gr	and Total:		\$56.04	

Serial Number: 71104997

Tracking Document Page 1 of 1

Repair Number: RE00323345

Repair Type

FIREARM Customer Repair

Serial Number Description

Model 710 Center Fire Caliber: 270 WIN

HIGH Priority

Repairman:

Date Received:

10/07/2013

Estimate Date: **Date Printed:**

10/08/2013

Return To:

RUSTY STAFFORD **4922 BEECH STREET**

BELLAIRE, TX 77401 US

Phone (H): 713-667-3281

Customer: RUSTY STAFFORD

4922 BEECH STREET

BELLAIRE, TX 77401 US

Phone (W):

Fax:

Email: staffordservices@yahoo.com

Problems Deported Found. M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Repair information

Material Number

Material Description

Material Type Bill Action Discount Qty Needed

Model:

Problem/Condition Notes

could not dup. concern Li direty asticky,

Clean Test Pattern Proof Repairman Date Date Gallery Tester Date Date Date

Accessories Received

1 - Less Mag Box

2 - With Stud









