

Remington Arms Co., Inc.
Product Service
Legal Case #:8698

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
304241	3/11/2013	3/13/2013	3/13/2013				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Richard	Lyons	31427 WCR51	Greeley	CO	80631		H 970-351-7166

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Mr. Lyons wrote a note & sent w/rifle: He said he inherited the gun from his father, did not find a purchase receipt, the rifle fired off when he pushed the safety forward to unload it. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	721/300 H&H MA	n/a	434110	CG	4/1/1960
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

3/15/13: Per Ilion - TA dirty & rusty. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/13/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	IMPROPER MAINTENANCE
Barrel	Description		24" 300 H&H MAG
	Date Code		CG
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.015
	Notch	Slightly Worn; Functioning	DIRTY,RUSTY
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY. PARTS WORK SLUGGISH
	Pull	---Select---	4#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	Other Remington	

Sir(s),

8698

2411
C64/66
4th
015

I inherited this rifle from my father. In going through all of his papers after he died, (5 years ago) we did not find any sort of sales receipt. He bought it new, in Colorado, in the late 1960's. That is about all I know on it. This is the gun that fired off when I pushed the safety forward to unload it at the end of a day of elk hunting. It hadnt done it before, during sighting in, and on the previous days hunts. Thank you for your attention to fixing it.

SR 00042116

300 H+H Magnum


Serial #

434110

Serial
Number:

434110

Model: 721



RE00304241

FSR

Richard Lyons

31427 WCR51

Greeley CO 80631

970-351-7166

T.A. Dinky + Rusty. My TPA,
clean + test and BLP for
20 +

RECEIVED
MAR 15 2013

BY:



