

Remington Arms Co., Inc.
Product Service
Legal Case #:8969

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
312527	6/4/2013	6/6/2013	6/6/2013				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Romero	Scigliano	309 Edinburg Ct	Southlake	TX	76092		H 817-416-8039 E romero.scigliano@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			Unknown
S	Fired when releasing the safety Concern:1007 Fired on Safe Release			
C				

6/12/13 Per note with rifle, this gun did discharge when he moved safety to off position with round in the chamber.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	721/3006 SPRG	n/a	244230	KYY	5/1/1952
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	27.40	6/12/2013				

6/12/13 Per Ilion, trigger assm dirty and set screws altered. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/6/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 3006 SPRG
	Date Code		KYY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Scar	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SEALANT MISSING ON PULL SCREW
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE, RINGS, TWO PIECE BASE

Madison, NC 27025-0700

Parts and Repairs: P-800-243-9700 F-336-348-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

244
12445/
2th

Service Request Number Serial Number / Description
SR00053909 244230
Model

Date of Request: 05/29/2013
Date Printed: 05/29/2013

8969

Customer:
ROMERO SCIGLIANO
309 EDINBURG CT
SOUTHLAKE, TX 76092 US

Destination:
Arms Services
14 Hostler Ave
Elion, NY 13357 US

Email: ROMERO.SCIGLIANO@GMAIL.COM

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number:
244230
Model: 721


RE00312527

RECEIVED
JUN 07 2013
BY:.....

T.A. dirty & set screws alt.
Rp. TAA, clean & reset and
BLP Ron & 20+

Q

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00

SR00053909

Model Number: 721 30-06		Serial Number: 244230	
Name: romero scigliano		Date of Purchase: 1986	
Address (to PO Boxes): 309 edinburgh ct			
City: southlake	State: tx	Zip: 76092	
Phone (Daytime): 817-416-8039		Fax:	
E-mail Address: romero.scigliano@Gmail.com			
Please describe your problem: Sending rifle in for Safety Modification program. This gun did discharge (fire) when I moved safety to off position with round in the chamber. Would also like to know if I can purchase replacement parts for front sling swivel? FYI - I have also sent in another 721 - serial number 257455 Thank you 181 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.			
<input type="button" value="Print"/>		<input type="button" value="Reset"/>	

FYI

#2 GUNS -> OTHER GUN
Serial # - 257455
SR00053910







