Remington Arms Co., Inc. Product Service Legal Case #:9422

Inform	

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 325900 10/30/2013 11/6/2013 11/6/2013 X

**Customer Information** 

First Last Type Business State Zip Age Street City Contact Name Name H 904-599-3679 1817 Autnumbrook Saint Incident Rich Berry FL 32259 E Lane Johns rberry01@comcast.net

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status ΡI PD Altered Adjustments or Cause:4006 Components Unknown FSO, FBR, and S **FSR** Concern: 1028 Fired With Safe ON

C

Per SR00064447 Service Request Section, "Rifle will fire with safety engaged. Rifle will fire when bolt is raised. Firearm will fire when safety moved from safe to fire." jbi

Firearm Information

Mfg. Type Model/Ga. **SKU** Bbl. DOM Serial CF/BA 722/222 REM N/A 419583 BF 1/1/1959 Remington **Date Purchased** Where Purchased Accessories **Original Owner** 

CONCERN: FSR,FRB,FSO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/722/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Settlement Release Date Reimbursement Release Date Release Date Reimbursement Release Date Release Date Reimbursement Release Date Release Dat

Per Ilion, quote to repair BLM

Repair/Replacement
Cost
\$25

11/7/13: Per Ilion, "trigger assembly dirty, set screws altered and cross pins altered. Replace trigger assembly, check over and test fire under bolt lock program for \$20.00 + shipping." jbi 11/15/13: I called and left message requesting approval of quote. jbi 11/22/13: Customer called Consumer Service and approved quote with a credit card. jbi

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9422&Type... 12/11/2013

PrintDisplay Page 2 of 3

Part	Sub-Part	Code	Соттепт
	Examiner		B.TRAVIS
	Exam Date		11/6/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
	Description		24" 222 REM
	Date Code		BF
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Worn; Functioning	SOME UPSET FROM LEAKING PRIMERS
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Worn; Not Functioning	
	Stock Condition	Worn; Functioning	]
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Slightly Worn; Not Functioning	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9422&Type... 12/11/2013

	Lift	Select	.006				
	Notch	Slightly Worn; Not Functioning	BINDING				
		Test Fired	False				
Feeding Test	Tests	False					
Trigger	Condition	Worn; Not Functioning	VERY DIRTY,STICKY,CROSS PINS ALTERED NOT FUNCTIONING				
	Pull	—Select—	1.5#				
	Altered	True	SET SCREWS ALTERED				
	Sub-Assembly	Other Remington					

# Quotation

## Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00325900	419	419583				Date Re Estimat Date Pr	e Date:	10/30/2013 11/06/2013 11/15/2013		
Customer: RICH BERRY 1817 AUTNUMBROOK LANE SAINT JOHNS, FL 32259 US				Return To:  RICH BERRY  1817 AUTNUMBROOK LANE  SAINT JOHNS, FL 32259 US						
Please Circle One										<del> </del>
VISA MC	DISCOVER	Card No	PO Numbou			Ex	p.Date			
Open Accoun	ι: κ		PO Number.							
Approval Signatu	re:						Date:			
Daytime Phon	e: ()		Time t	o Call:						
		lease use the reverse si						-		
		OUCT SERVICE FOR Y MODIFICATION				ARD TO PRO LOCK SAFE			INSPE	CTION
			Technician							
trigger assembly of + shipping	-	altered and cross pins	-		-				gram for	r \$20.00
Material	Type	TIMATE (note: C.O.D Description	)./Shipping and Han	. (	arges aı Qty eded	re NOT Includ Warranty	led in this Q Qty From Inv	uote.) Price	Disc	Amount
F202906 4000114 4000116 4000119	Part Service Service Service	40 SSA TRIG ASSB GR-SHIPPING & HA GR-LABOR GR-TEST			1 1 20 1	Warranty Billable Billable Warranty	1 1 20 1	.00 17.00 1.00 .00		.00 17.00 20.00 .00
							Est	o Total: Sales Tax:		37.00 2.22 \$39.22

ru nox /uu

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. The serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOC YOUR RETURN.

Service Request Number / Description

SR00064447

419583 Model 722

Customer: RICH BERRY

1817 AUTNUMBROOK LANE SAINT JOHNS, FL 32259 US

Email: rberry01@comcast.net

Date of Requesti 0/15/2013

Date Printed10/15/2013

Destination: Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

BF1/2

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

From SAFE TOFICE

Parts And Service Details

Material Type D

Description

Qty Needed

Warranty

Price Disc Amount

Model:



BY:----

T.A. dinly set screws + cross
pins Alt. - Rep T. D. checkoven
Test und BLP fon 70+

Sub Total: Est Sales Tax: .00 .00

**Grand Total:** 

\$.00

#### Schults, Colleen M.

From:

Cobbler, Tracy S.

Sent:

Monday, November 04, 2013 4:07 PM

To:

Fulcher, Dell Marie; Nichols, Scott C.; Schults, Colleen M.

Cc:

Matousek, Rob A.; Travis, Bruce W.

Subject:

RE: SR64447

I have attempted several times to contact the customer to no avail if I do remember correctly his neighbor called and set it us so just use the information that is listed on the service request.

From: Fulcher, Dell Marie

Sent: Monday, November 04, 2013 3:38 PM

To: Nichols, Scott C.; Schults, Colleen M.; Cobbler, Tracy S.

Cc: Matousek, Rob A.; Travis, Bruce W.

Subject: RE: SR64447

Everything I see on the SR should be under Rich Berry's address.

No clue who Doug Disbrow is.

### **Dell Fulcher** | Consumer Affairs Administrator Remington Arms Company, LLC

PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 ext 8686 | Fax: 336.548.7872 Email:

#### dell.fulcher@remington.com

Freedom Group Family of Companies: Remington | Marlin | Bushmaster Firearms | DPMS / Panther Arms | H&R | Barnes Bullets | Advanced Armament Corp | Mountain Khakis | Dakota Arms | Parker Gun | Para USA

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system.

From: Nichols, Scott C.

Sent: Monday, November 04, 2013 3:21 PM To: Schults, Colleen M.; Cobbler, Tracy S.

Cc: Matousek, Rob A.; Fulcher, Dell Marie; Travis, Bruce W.

Subject: RE: SR64447

We just need the réturn address. Bruce can review and create the product service exam.

From: Schults, Colleen M.

Sent: Monday, November 04, 2013 2:44 PM

To: Cobbler, Tracy S.

Cc: Matousek, Rob A.; Nichols, Scott C.

Subject: FW: SR64447

Hi Tracy,

We you able to find out anything on the below e-mail?

Thanks,

Colleen

From: Schults, Colleen M.

Sent: Wednesday, October 30, 2013 11:21 AM

**To:** Cobbler, Tracy S. **Cc:** Nichols, Scott C. **Subject:** SR64447

Hi Tracy,

We received the above firearm. It was sent in from another individual Doug Disbrow, 5509 Shad Road, STE 2 Jacksonville FL 32257, phone #904-631-7349. The SR is made out to a Rich Berry of Saint Johns, FL. This gun will be a product service gun as it fires with the safety on.

Could you please find out who it should go back to.

Thanks,

Colleen









