Remington Arms Co., Inc. Product Service Legal Case #:9142

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 319199 8/27/2013 8/28/2013 8/28/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter

Incident Don Brien 36 Armory St. Ilion NY 13357 H 315-894-8678

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI PD

Cause:4015 Improper Maintenance

Unknown

S FSO Concern:1028 Fired With Safe ON

C

Per Firearm Delivered to the Plant for Repair Form, gun fires on safe. jbi

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 722/300 SAV
 N/A
 42269
 RTT
 11/1/1948

Date Purchased Where Purchased Accessories Original Owner

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/722/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Release Date Relea

Offer to replace trigger assembly, clean, and test at 50% discount

Repair/Replacement Repair/Replacement Cost Date

8/29/13: Per Ilion, "trigger and trigger pin rusted causing trigger to bind back. Replace trigger assembly, check over and test fire at 1/2 normal cost." jbi 8/30/13: Called customer with quote, and he approved with credit card. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment				
	Examiner		B.TRAVIS				

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9142&Type=... 8/30/2013

	Exam Date		8/28/2013
	Product Type]	RF
Examination	Action Type]	A
	Assigned To]	S.NICHOLS
Cause	4015	Improper Maintenance	NEW STYLE TRIG ASSM WAS REPLACED 3/04 R# 78651
	Description		24" 300 SAV
	Date Code		RTT
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Wom; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False]
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.012

 $http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9142\&Type=... \ 8/30/2013$

Sear	Notch	Slightly Worn; Functioning	,
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG AND TRIG PIN RUSTED CAUSING TRIG TO BIND BACK, NOT RETURN WILL FOLLOW DOWN
т.	Puil	Select	10+#
Trigger	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00319199	•	Serial Number / Description 42269 Model 722 Center Fire Caliber: 300 SAV			Date Re Estimat Date Pr	e Date:	08/27/2 08/28/2 08/30/2	013
Customer: DON BRIEN 36 ARMOR ILION, NY	Y STREET		Return To: DON BRIEN RETIREE 36 ARMORY STREET ILION, NY 13357 US					
Please Circle On VISA MC Open Accou	DISCOV	/ER Card No PO Number:		Ехр.	Date			
Daytime Pho	ne: ()Time to ge, please use the reverse side for your comment	to Call:s and mark this b					
Reported M123 - FORV	VARD TO P	Product Service for Inspection	blems Found M123 - FORV	WARD TO PROI	DUCT SER	VICE FOR	INSPE	CTION
trigger and trigg	er pin rusted	Technician I causing trigger to bind back, replace trigger ass	Comments	er and test fire at	1/2 normal	cost.		
		ESTIMATE (note: C.O.D./Shipping and Han						
Material	Туре	Description	Qty Needed	Warranty	ed in this Q Qty From Inv	Price	Disc	Amount
F202906 4000119	Part Service	40 SSA TRIG ASSB RH GR-TEST	1 1	Billable Billable	1	87.00 23.00		43.50 11.50
					Est	Total: Sales Tax:		55.00 3.85 \$58.85



	Receipt Of Firearm(s) Deliver	ed to the Plant for Repair r Live Ammunition	Agn: Dele Lewis 24"
	Driver's License ID# 842-199-0-79	r rac Ammundon [7]	2011/48
	Delivery Date <u>3 /26 / 10</u>	9142	RT 11/48 RT 11/48 RT 11/48 Employee (X) (N) 1012
	Customer Name (Print)		
•	Address 31 ARMIRY	City	
	State Zip)- 594-9678
<u>-</u>	Manufacturer Rem INA LON Firearm Description Model 72.2	Cal./Ga	O SOMAGE
, **	Serial Number	Synthetic, Wood)	
	Metal Condition - circle the description (Excellent, Good, Fair, Poor, Fancy, Plain S Comments on Metal condition	Stainless Steel)	
	Barrel Type (VT. Rib; Plain; Deer; Stainless S List additional accessories: IE Scope, Sling, C	-	
	Customer request: FIRES CAN	SAFE	
	Return Process Return to Clark St. Ent. 12 Re	eturn via UPS []	·
	By signing this receipt the person delivering person to receive the firearm upon complet		be the only
	Signature Almand T. Ban	. 201 Date 8 12/11	E TRIGHTRIG. DIN RUSTED
	person delivering fiream	n	CAUSING TRIG. DIN RUSTED BARK. Replace T.A. Checkoven Test Fire
	Signature Security officer		#1 /2 cosr.
	Signature And Ann Relient	Date 8 1271	
≕Ľ	_	ι Up Verification ered the above described fi	40 Ab
42 2	269	lawfully possess a firearm i	n New York State.
Model:	722	Date	/_ AIG 2 9 2013
		Date	/ BY:
F	KE00319199	cturning the firearm	
		Kei	nington.
	Security Copy - White Arm Service	: Ćopy - Yellow Custo	mer Copy - Pink







