

Remington Arms Co., Inc.
Product Service
Legal Case #:8970

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
312814	6/6/2013	6/7/2013	6/7/2013				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Don	Moyer	2232 S 12 St	Burlington	IA	52601		H 319-850-2856 E mo31016@juno.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			
S	Fires when bolt is closed Concern:1008 Fired on Bolt Closing		Unknown	
C				

6/12/13 Per note with rifle, bad trigger. Fires when bolt is closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	722/222 REM	n/a	169712	AXX	3/1/1951
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/722/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price.						
	Repair/Replacement Cost	Repair/Replacement Date				
	15.40	6/12/2013				

6/12/13 Per Ilion, trigger assm set screws altered. Replace TPA, clean, test at BLSM program price. Will need BOA to complete repair.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/7/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	BOLT REC'D IS FOR A 308 CAL. CANNOT USE FOR FUNCTION
Barrel	Description		26" 222 REM
	Date Code		AXX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	WRONG BOLT SENT IN WITH ACTION
	Stock Condition	---Select---	REC'D LESS STOCK
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Slightly Worn; Functioning	
Sear	Lift	---Select---	.014
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	HAS EXCESSIVE PRETRAVEL
	Pull	---Select---	2#
	Altered	True	SET ACREWS ALTERED SEALANT MISSING
	Sub-Assembly	Other Remington	

Remington Arms - Support - General Repair Form

Page 2 of 3

Home » Support » Repair Services » General Repair Form

SHARE



Product Registration
Help Center
Repair Lookup
Repair Services
Warranty
Retail Locator
Versa Max Warranty
Parts Information
Contact Us

GENERAL REPAIR FORM

Model Number: 722		Serial Number: 169712	
Name: DON MOYER		Date of Purchase:	
Address (no PO Boxes): 2231 S. 12th St.			
City: BURLINGTON	State: IA	Zip: 52601	
Phone (Daytime): 319 850 2856	Fax:		
E-mail Address: MOE1016@JUND.com			
Please describe your problem: BAD Trigger. Fires when BOIT is closed.			
500 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<input type="checkbox"/> WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE REARM.			

Number: 169712

Model: 722



RE00312814

ending it.
damage in
(turned.)
ent loss or
cel Post.
oss
nce from your

T.A. set screws Alt. rep. TPA.
clean + test and. RCP Rore 20 +
will need BPA. to complete rep.

Q







