### Remington Arms Co., Inc. Product Service Legal Case #:9362

Case Infor	mation								
RE#	Date Opened	Date Opene	d(PS) E	ate Closed	Incident	Date	Pre Lit	Lit	Obsolete
325595	10/28/2013	10/29/20	13	0/29/2013					
Customer	Information								
Type B	usiness First Na	me Last Name	Street	City	State Zip	Age	С	ontac	t
Incident	Brian	Abramowski	84 Magill	St Manistee	e MI 49660	E	H 231 skidaddy9		4468 otmail.com
Incident In	formation								
Cla	ims	C	odes		Repair Est.	-	Medical reatment	j	Medical Status
PI bruise should PD	ler	::4006 Altered Compo	Adjustment nents	is or			U		
S FSR C	Conce	ern:1007 Fired o	n Safe Relea	se					

Per SR00064430 Service Request Section, "When moving from safe to fire, gun with go off. Happens about every 15th time gun is used. If gun is upside down, gun will go off." Per letter from Brian Abramowski, gun fired on safe release while his son was deer hunting with it. "Not only did my son miss his first buck, he also had a black and blue shoulder." jbi

Firearm Informat Mfg.	ion <b>Type</b>	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	770/3006 SPRG	85633	71380134 PB	6/19/2007 4:57:10 PM
Date Purchased	Where Purchased	Accessories	Original Owner		
	DUNHAM S SPORTS	SCOPE,RINGS,BASE	U		
CONCERN:FSR					

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

#### Remington/770/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV	
Replacing with Ramac 84371 in exchange at a 50% discount							
	Repair/Replacement Cost	Repair/Replacement Date					

10/30/13: Per Ilion, trigger set screws altered. Trigger not returning under sear. Replace trigger assembly, check over, and test at 1/2 normal cost. jbi 11/1/13: I call and left message for Brian Abramowski to return my call. I

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9362&Type... 11/12/2013

÷

received call back from Mr. Abramowski, he said that he is willing to pay the difference between the Model 770 and the Model 700 VTR in 243 WIN. I advised that once replacement is quoted, that I will call him back. jbi 11/4/13: I emailed llion to quote replacing with a Model 700 VTR (Ramac 84368) in exchange at a 50% discount. jbi 11/5/13: I called and left quote on customer's voicemail. jbi 11/6/13: I received call from Brian Abramowski, he said that he is not sure if he wants a 243 WIN or 308 WIN. He said he will let me know by Friday (11/8/13). jbi 11/8/13: I received call from Brian Abramowski, agreed to having his rifle replaced with Model 700 VTR (Ramac 84371) at a 50% discount. He approved with a credit card. Ramac 84371 order on SAP order 1560561. jbi 11/1/13: FFL information received. Removing shipping hold. jbi 11/12/13: I received voicemail from Brian Abramowski. I returned his call and left him a message letting him know that the FFL info has been received. jbi

Sub-Part Code Comment Part **B.TRAVIS** Examiner 10/29/2013 Exam Date Examination Product Type RF Action Type A Assigned To S.NICHOLS Altered Adjustments or Cause 4006 Components 22" 3006 SPRG Description PB Date Code False Bore Plugged False Bulged Barrel Fired False Fired while Obstructed Muzzle/Crown Slightly Worn; Functioning Condition Firing Pin Slightly Worn; Functioning Shroud Slightly Worn; Functioning Slightly Worn; Functioning Bolt Face Handle Slightly Worn; Functioning Stop Slightly Worn; Functioning Condition Slightly Worn; Functioning Extractor Cut Condition Slightly Worn; Functioning Ext/Eject Test False **Block Condition** --Select---Locking Slightly Worn; Functioning Lug Condition Notch Condition -Select-Condition --Select---Magazine Slightly Worn; Functioning Box Condition Slightly Worn; Not Exterior Condition Functioning Overall Stock Condition Slightly Worn; Functioning

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9362&Type... 11/12/2013

	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description	]	STANDARD SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING UNDER SEAR WILL FOLLOW DOWN
Trigger	Pull	Select	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9362&Type... 11/12/2013

-

U.S. Department of Justice Bureau of Alcohol, Tobacco, Firearms and Explosives	Federal Firearms License (18 U.S.C. Chapter 44)						
	regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the United States Code, and the regulations issued thereunder, until the expiration date (8.51. See "WARNINGS" and "NOTICES" on reverse.						
Direct ATF ATF - Chief, FFLC Correspondence To 244 Needy Road Martinsburg, WV 25405-9431	License Number 4-38-101-01-5G-03516						
Chief, Federal Fireagers Licensing Center (FFLC)	Expiration Date July 1, 2015						
Name UL RLK SALES							
Premises Address (Changes? Notify the FFLC at least 30 days before the move.) 618 PINE ST MANISTEE, MI 49660-							
Type of License 01-DEALER IN FIREARMS OTHER THAN DESTRUCTIV	E DEVICES						
Purchasing Certification Statement       Mailing Address (Changes? Notify the FFLC of any changes.)         The licensee named above shall use a copy of this license to assist a transforor of firearms to verify the ideatity and the licensed status of the licensee as provided by 27 CFR Part 478. The signature on each copy must be an original signature. A faxed, scanned or e-mailed copy of the license with a signature intended to be an original signature intended to be an original signature intended to be an original signature is acceptable. The signature must be that of the Federal Firearms Licensee (FFL) or a responsible person of the FTL facetify that this is a true copy of a license issued to the license named above to change in the business specified above under "Type of License."       Mailing Address (Changes? Notify the FFLC of any changes.)         JACEBSEC/Responsible Person Signature       Position/Title       Mailing Address (Changes? Notify the FFLC of any changes.)							
Printed Name Date States Maliferrans and States and Sta	3. ATT Form 8(5310:11) Revised Oxfore 2011						
Federal Firearms Licensing Center (FFLC)         Federal Firearms Licensing Licensing Center (FFLC)           244 Needy Road         Toll-free Telephone Number:           Martinsburg, WV 25405-9431         E-mail: NLC@atf.gov	er: (866) 662-2750 (866) 257-2749 AIF Homepage: www.atfgov (866) 257-2749 FFL eZ Check: www.atfonline.gov/fflezcheck						
Change of Address (27 CFR 478.52). Licensees may during the term of their current license remove their business or activity to a new location at which they intend regularly to carry on such basiness or activity by filing an Application for an Amended Federal Firearms License, ATF Form 5300.38, in duplicate, nor less than 30 days prior to such removal with the Chief, Federal Firearms Licensing Center. The application must be executed under the penalties of penjury and penalties imposed by 18 U.S.C. 924. The application shall be accompanied by the licensee's original license. The license will be valid for the remainder of the term of the original license. (The Chief, FFLC, shall, if the applicant is not qualified, refer the application for amended license to the Director of Industry Operations for denial in accordance with § 478.71.)							
Right of Succession (27 CFR 178.56). (a) Certain persons other than the licensee may secure the right to carry on the same firearms or emmunition business at the same address shown on, and for the remainder of the term of, a current license. Such persons are: (1) The surviving spouse or child, or executor, administrator, or other legal representative of a deceased licensee; and (2) A receiver or trustee in bankruptcy, or an assignee for benefit of creditors. (b) In order to secure the right provided by this section, the person or persons continuing the business shall furnish the license for that business for endorsement of such succession to the Chief, FFLC, within 30 days from the date on which the succession begins to carry on the business.							
Cut Here X	(Construed on reverse side)						
Federal Firearms License (FFL) Information Card	FFL Newsletter - Electronic Version Available						
License Name: KIESZKOWSKI, FYAN LEE							
Business Name: RLK SALES	Sign-Up Today!						
License Number: 4-38-101-01-5G-03516	FFLs interested in receiving the electronic version of the FFL Newslet- ter, along with occasional additional information, should submit name. FFL number, and e-mail address to: FFLNewsletter@atf.gov.						
License Type: 01-DEALER IN FIREARMS OTHER THAN DESTRUCTIVE DEVICES	The electronic FFL Newsletter will enable ATF to communicate						
Expiration: July 1, 2015	information to licensees on a periodic basis.						

Please Note: Not Valid for the Sale or Other Disposition of Firearms.

.

Nov 08 13 09:32p Oak Grove Cremation

RLK Sales 618 Pine Street Manistee, MI 49660 (231) 794-9320 (231) 723-1029 fax

To: JB

From: RLK Sales

Date: Nov. 8, 2013

Subject: Ref # 9362

JB

Here is a copy of my FFL so you can ship the above referenced firearm to me.

If you have any questions please contact me. Thank you

Ryan L. Kieszkowski

C31-723-1029 p.1

## Quotation

•

.

#### Remington Service PO Box 700

# Estimating Report

Madison, NC 27025-0700 www.remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

<b>Re</b> pair Number RE00325595	71	rial Number / Description 380134			Date Received: Estimate Date:	10/28/2	013
	Mo	odel 770 Center Fire Caliber: 30 -06 SPRG			Date Printed:	11/05/2	013
Customer:			Ret	urn To:			
BRIAN ABRAMOWSKI 84 MAGILL STREET				BRIAN ABRAM			
MANISTEE.		iS		MANISTEE, MI			
, in a do t bil,				,,			
Please Circle One	:						
VISA MC	DISCOVER	Card No PO Number:		Ехр.І	Date		
Open Account	t: R	PO Number:					
					Data		
		Time to Ca					
		please use the reverse side for your comments and					••••
		Problem					
Reported			und				
		DUCT SERVICE FOR INSPECTION MI	23 - FOR	WARD TO PROD	UCT SERVICE FO	R INSPE	CTION
M568 - SAFET	Y BRUKEN						
tuissen opportelus	at concurs alta	Technician Con red.trigger is not returning under sear.replace trig			in auchanza at 500	/ discour	t for rom
ac# 84368	set screws alte	red.urgger is not returning under seat.reprace trig	ger assento	ly, quote to replace	e in exchange at 50	o uiscoui	
	ES	TIMATE (note: C.O.D./Shipping and Handlin	Charges	are NOT Included	in this Quote.)		
Material	Туре	Description	Qty	Warranty	Qty Price	e Disc	Amount
4000114	<b>0</b> . <b>1</b> .		Needed		From Inv		0.0
4000114 4000254	Service Service	GR-SHIPPING & HANDLING (GUN REPAIR GR-FIREARM REPLACEMENT	.) 1 08	Warranty Billable	1 .00 08 1.00	0 050	.00 454.00
l							
					Sub Total:		454.00
					Est Sales Ta	x:	. 00
					Grand Tota	ŀ•	\$454.00
<u> </u>					Granu 10ta	•	+-31.00

Parts and Rep	pairs: P:800-243	3-9700/F:336-548-7801	www.remingto	n.com					
THIS IS NOT AN I	NVOICE. THIS IS A	EXCHANGE FOR REPLACED N ESTIMATE TO REPAIR, RECONDIT LOW AND RETURNING TO THE ABO	ION, OR REPLACE THE VE ADDRESS. REPAIR	ITEM(S) D	APPROXIMATELY	W. IF THIS IS S/ (6) WEEKS AFT	ATISFACTO ER RECEIP	RY, T OF APF	ROVAL.
Repair Number RE00325595	er Se 71	ROVAL IN 21 DAYS, WE WILL RETUR		EIVED, PO 	STAGE DUE.	Date Rec Estimate	Date:	10/28/2	013
	м	odel 770 Center Fire Caliber: 3	0 -06 SPRG			Date Pri	nted:	10/31/2	013
	BRAMOWSKI L STREET				<b>rn To:</b> BRIAN ABRA 84 MAGILL S'	TREET			
MANISTE	E. MI 49660 l	JS			MANISTEE, I	MI 49660 US	5		
Please Circle C VISA M	C DISCOVE	R Card No			Ex	p.Datc			
Open Acco	unt: R	PO N	umber:						<del></del>
Approval Signa	ature:		Time to Call:			_ Date:			
I If you de	sire any change.	please use the reverse side for y							
			Problems			· · · · · · · · · · · · · · · · · · ·			
M123 - FOR	WARD TO PRO ETY BROKEN	DUCT SERVICE FOR INSPE	CTION M123	-	WARD TO PRO	DUCT SERV	VICE FOR	ÎNSPE	CTION
trigger assembl	ly set screws alte	red.trigger is not returning unde	Technician Comn er sear.replace trigger	nents assembl	y, check over an	d test fire at	1/2 normal	cost.	
Material	Туре	TIMATE (note: C.O.D./Shipp Description		Charges a Qty Needed	Warranty	ded in this Q Qty From Inv			Amount
F301265 4000114 4000119	Part Service Service	710 REC. INSERT ASSB. C GR-SHIPPING & HANDLIN GR-TEST	OMPLETE	1 1 1	Billable Billable Billable	1 1 1	60.00 17.00 23.00	0	30.00 17.00 11.50
							Total: Sales Tax	:	58.50 1.80
						Gra	nd Total:		\$60.30

.

Quotation

۰.

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

#### PS 31044

# Service Request

# Remington Service PO Box 700

Madison, NC 27025-0700



2#

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number Serial Number / Description Date of Request: 10/15/2013 SR00064430 71390134 Date Printed: 10/15/2013 Model 770 RIFLE Customer: BRIAN ABRAMOWSKI **Destination:** Arms Services **84 MAGILL STREET** 14 Hoefler Ave MANISTEE, MI 49660 US Ilion, NY 13357 US Email: skidaddy911@hotmail.com Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your frearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return -. M568 - SAFETY BROKEN Service Request Section and the second When moving from saf eto fire, gun with go off. Happens about every 15th time gun is used. If gun is upside down, gun will go off. - EVERY TIME Will huppen more often w/ Round Parts And Service Details Price Disc Amount Qty Material Type Warranty Needed NECEIVE NCT 3 0 2013 BY:-----Also PLEASE see Enclosed lefter! THANK YOU T.A. Set Screws Alt. TRIG Not REKURNING LEND. SEAR. B71380134 Ryp. T.A. checkoven thest. 71 Model: AT 1/L NOT WAL COST. ; item(s) Sub Total: .00 RE0032559 Est Sales Tax: .00 Grand Total: \$.00

#### To whom it may concern

#### **REF # SR64430** Remington model 770 (30-06) serial # 71390134

I am writing this letter in regards to the remington 770 serial # 71390134. I am not happy at all with the safety and performance of this rifle that I currently own. My son who is 15 years of age was using this rifle on the third day of deer season in Michigan. I was sitting in my field blind and he was sitting down in the swamp blind 300 yards away. I heard a shot and I thought to myself great I know he has one laying dead, because he's a great shot and was driving tacks when we were target shooting with this rifle, when I got out of my blind and walked down to the swamp blind. I asked him where is it? He looked at me with this blank and confused look on his face and said there was a six point walking into an opening so he raised the gun to the window and switched the safety from safe to fire and before he could even get his eye up to the scope the gun fired. I said what are you sure did you have your finger on the trigger when you switched it to fire? He said no my finger was no ware near the trigger, just as I had taught him. So he got out of blind and ejected the spent round and removed the clip and left the bolt in the open position, leaned it against a tree and waited for me. After our conversation I began to inspect the rifle because I thought no way he had to have had his finger on the trigger but he was right. About 20 minutes later I figured out that with a round in the chamber or not about 1 out of 15 to 20 times it would fire the pin when I removed the safety. The pin did fire more often when there was a round in the chamber, also when I got home and did some more investigating I figured out when you flip the rifle completely upside down and go through the same process it fired the pin every time, I am an avid hunter and I have been around guns all my life. I own several firearms and I have never seen this in my 28 years of hunting or being around firearms. I am a military veteran and spent 4 vears in the U.S Army and know how to clean and take care of and respect firearms. I do own another Remington 700 BDL(270) and have never had a problem with it, as a matter of fact it is my favorite rifle but I am just glad that no one got hurt or even killed over this safety issue. Not only did my son miss his first buck, he also had a black and blue shoulder. I don't care that he missed his first buck, I was more upset with the safety aspect of the rifle. I taught my son that keeping the barrel pointed in a safe direction at all times and the safety of the rifle and cleaning was the most important thing when it comes to firearms. Even if this gun is repaired I would not trust it or use it in the future, and would not have a good conscious in selling it. If at all possible I would like a different gun in replacement of the 770 and if possible I would like the model 700 VTR in a 243 for my son cause as of now he is a little gun shy with the whole safety situation. And I figure this will help him. I am willing to pay the difference in guns, I am not trying to get something for nothing, but I do not want this rifle back. I am not trying to discredit Remington at all they make great rifles and great ammunition as I said before I love my BDL and I would like to thank Lisa Rice from Remington for all her help during this process. Her patience and understanding is greatly appreciated. Thank you again

Brian Abramowski 84 Magill St. Manistee, MI 49660

Brian aluaroush.

skidaddy911@hotmail.com (231-233-4468)







