PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service

Legal Case #:8614 Case Information Date Opened RE# Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 299884 2/7/2013 2/14/2013 2/14/2013 **Customer Information** Business First Name Last Name Street City State Zip Age Contact Academy Sports 310 Doug Baker Blvd. Birmingham AL 35242 W 205-981-4174 Reporter Academy Sports & Outdoors Incident Information Claims Codes Repair Est. **Medical Treatment** Medical Status ΡĮ PD Cause:4038 Could Not Duplicate Concern Unknown Concern:1007 Fired on Safe Release S FSR Dealer sent rifle in w/note - will not chamber a round unless turned on the left side... bolt sticks badly... mag. is difficult to seat when loaded... has fired when the safety was released. df Firearm Information SKU Mfg. Type Model/Ga. Serial Bbl. DOM 770/3006 SPRG 85653 M71651851 AF 3/23/2011 12:59:56 AM Remington CF/BA Where Purchased **Original Owner** Date Purchased Accessories ACADEMY LTD SCOPE, RINGS. BASE U CONCERN: FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/770/CF/BA Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV Per Ilion - Repair @ Repair/Replacement Repair/Replacement Date Cost \$27 2/18/13: Per Ilion - Could not duplicate concern, to restore confidence in rifle will replace TA, check over, correct feed issues & test fire @ n/c. df Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		2/14/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 3006 SPRG SS
	Date Code		AF
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8614&Type=Case

2/22/2013

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Wom; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overali	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	N/A
Scar	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
T-:	Condition	Slightly Worn; Functioning	
	Puli	Select	4#
Trigger	Altered	False	
	Sub-Assembly	Other Remington	

	Customer Firearm Repair - Info for Manufacturer/Repair Center				
Today's Date	2/2/2013		ي معيد	221	
Completed By	mike bryant	8614	•	8×31	
Manufacturer/Repair Center Information:			·	,	
Manufacturer/Repair Center Address	Remington Arms Co Attn: Arms Service I 14 Hoefler Ave. Ilion, NY 13357	•			
Phone Number Website	1-800-243-9700 www.remington.com				
Notes	0			:	
Serial Number	m71651851	1			
Model	770	could a	rot duplicate of splety release uncein Rift will ecknower correct place of the correct place	ONCERN,	
Type of Firearm	rifle	confide	incein Rifkwil	1 juplace	
Caliber/Gauge	30-06	TPA, Ch	eckouen copped	.t Leed ( SSU	
sku	14256770	* Kos,	11/6		
Reason for Repair	will not chamber a rolls difficult to seat where the control of th	ound unless turned on the legen loadedhas fired whe	oft sidebolt sticks ba on the safty was released	dlymag.	
RA # (if applicable)	0	A. Carrier			
Return Address	Please return the fire Academy Sports + 0 Attention: MOD	earm to the following addres Outdoors	s once the repair is comp	olete: •	



Store Phone Number

FSP

205-981-4174

PECEIVE I FEB 18 2013 BY:





