Remington Arms Co., Inc.
Product Service
Legal Case #:8608

			Legal C	Case #:8608						
Case Information						_				
RE# 300190	2/11/2013	Date Open 2/12/20		Date Closed 2/12/2013	Incident Date	: l	Pre Lit	Lit	Obsolete	
Customer Infor	mation									
Type Busin	ness First Name	Last Name		treet	•	State	Zip A	ge	Contact	
Incident	Ray	Carrales	6606 HAWTHO	RNE FALLS LANE	Houston	TX 7	7049	H	832-589-574	
Incident Inform	ation									
Claims		Codes				Repair Medical Medical Est. Treatment Status				
PI										
PD		Cause:4015 In								
S Rifle fired when he started to lift bolt		Concern: 1025 S	f Unknown							
C CD# 42821 C-	D C			l da life ah a haladha a	:a- c 1 1c					
SR# 42821 - Se	rvice Request Sect	ion: Consumer sa	d when he started	to lift the bolt the r	ille fired, df					
Firearm Inform	ation									
Mfg.	Тур		Model/Ga.	SKU	Scrial	Bbl.			OM	
Remington			MM REM MA	85654	M7168911	7 CF	7/13	/2011	11:35:40 AM	
Date Purchas	sed Where Pui ACADEM		Accessories	Original Owner U	•					
CONCERN: FI	ACADEM RED LIFTING BC									
,					<u></u>				,-////	
Ammunition In	formation - None I	Defined								
Other Products	Information - None	Defined								
Settlement										
			Remingto	n/770/CF/BA						
Settle	ment	Release of Claim	s Releas	e Date Reiml	bursement c	Cash ettlemei		im. Da APV	ite Cash Dat APV	
Per Ilion - Re	epair @ n/c -				3	etteme		AL Y	AIV	
goodwill	_									
	K	epair/Replacemo		placement ate						
		\$41								
		oly rusty. Sear rus	ted to side plate.	As a goodwill gestu	re to restore co	nfidence	in rifle,	will re	eplace TA,	
clean & test at r	√c. df									
T										
Examination[Ki	emington/CF/BA]				·					
Part	Sub	-Part		Code			Comm	ent		
Examination	Examiner				B.TRAV	TS			<u> </u>	
	Exam Date		İ		2/12/2013					
	Product Type		j		RF					
	Action Type		Ī		A	A				
	Assigned To				S.NICHO	DLS				
Cause	4015		Improper Mainte	nance						
Barrel	Description				24" 7MM REM MAG SS					
	Date Code				CF	CF				
	Bore Plugged		False							
	Bulged		False							
	Fired		False							
1	Fired while Obs	tructed								

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8608&Type=Case

2/22/2013

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	I Iandle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	SEAR RUSTED TO SIDE PLATE
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700



Date of Request:

01/23/2013

Printed: 01/23/2013

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

SR00042821

M71689117

Model 770 RIFLE

Customer: RAY CARRALES

6606 HAWTHORNE FALLS LANE

HOUSTON, TX 77049 US

14 Hoefler Ave

Ilion, NY 13357 US

Ray, Carrales @ aclines, com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M129 - FAILS TO EXTRACT

M992 - BOLT

Service Request Section

CONSUMER SAID WHEN HE STARTED TO LIFT THE BOLT THE RIFLE FIRED.

TIGHT CHAMBER.

Parts And Service Details

Material

Type

Description

Oty Needed

Warranty

Price

Disc Amount

Model:

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Trig. ASSM Dusty. Sear Dusted to sideplate. AS A Good-will opsture to justone confi in piffe will hep. TPA, cleans rest At N/C

260934

Sub Total: Est Sales Tax:

.00 .00

Grand Total:

\$.00



ACADEMY WESTHEIMER/VOSS 713-268-4300

12/29/12 18:16 274433 SALE 5045 0116 206

REMINGTON 770 7MM / 14256788

SERIAL # M71689117

1 & 1 for 339.99 MDS 339.99 SUBTOTAL 339.99 8 25% SALES TAX 28.05

TOTAL 368.04

DEBIT CARD 150.00

XXXXXXXXXXXX4506

EFT Debit Payment from Primary

Sequence #1430

RAY CARRALES AUTH 030539 GIFT CARD 150.00

AUTH 010691

CARD BALANCE:

.00

<<ELEC SIGNATURE CAPTURED 5045 1 >>

American Express 68.04

\$

XXXXXXXXXXXXX8475

EXP

A GIFT FOR YOU

AUTH 316761

RIGHT STUFF, LOW PRICE. EVERYDAY!

THANK YOU! SHOP 24/7 AT ACADEMY.COM

12/29/12 18:18





