Remington Arms Co., Inc. Product Service Legal Case #:9517

				Pro	duct Service	е							
				Lega	d Case #:95	17							
Case Inform	ation												
RE#	Date Opened	Date	Opened	ened(PS) Date Close		ed :	Incident	Date	Pre l	Lit I	it O	bsolete	
330361 12/10/2013		11	1/18/201	3	12/11/201	3							
Customer In	formation												
Туре	Business	First Name	Last N	lame	Street	:	City	State	Zip	Age	Cor	ıtact	
Reporter	Eldorado Pawn		El Doi Paw		107 We Hillsbo		El Dorado	AR	71730	ı		0 -863- 544	
Incident Info	ormation												
Claims		Co	des		Re	epair E	st. Me	dical Tr	eatme	nt N	le dical	Status	
ΡΙ													
PD	Cause: 4038	Could N	Not Dupl	icate Co	ncern			T I1					
S FBC	Concern:10	008 Fired or	n Bolt Cl	losing				Unkno	own				
С													
11/18/13: I t	received call f	rom El Doi	ado Paw	n, they a	are sending	gun in 1	for custo	mer who	said t	hat th	e gun f	ired on	
bolt closing.	jbi												
	. •		1										
Firearm Info		_	,			0777	•	Serial			200		
Mfg.	.]	Туре		Model/Ga.		SKU	SKU		Bb		DOM		
Remingto	on C	F/BA	770/308		VIN	8563	4 M	171914509 AH		i 3/8	3/8/2013 2:09:48 PM		
Date Purchase	d Where	Where Purchased		Accessories		Origin Own						•	
		rs south LLC	SCOP	E,RING	S,BASE	U							
CONCERN	: FBC												
	n Information												
				Remin	gton/770/CF	F/BA							
									Cach		Reim.	Cash	
Settlem	ent Re	lease of Cl	aims	Rel	ease Date	Rei	mbursei	nent S	ettlem	ent	Date	Date	
Per Ilion, r TPA, chec and test a	k over at no										APV	APV	
_		air/Replac Cost \$41	ement	Repair/	Replaceme Date	nt							
	ending ARS, l in rifle will re	etter, and S								conce	rn. To	restore	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9517&Type=... 1/14/2014

PrintDisplay Page 2 of 3

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/11/2013
	Product Type		RF
	Action Type		A
	Assigned To	7	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 308 WIN
	Date Code		AH
	Bore Plugged	False	
Barrel	Bulged	False	Ę
	Fired	False	=
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	=
	Shroud	Like new; Functioning	Ħ
Bolt	Face	Like new; Functioning	=
	Handle	Like new; Functioning	==
	Stop	Slightly Worn; Functioning	===
	Condition	Like new; Functioning	=
Extractor	Cut Condition	Like new; Functioning	=
2/10/10/01	Ext/Eject Test	False	=
Locking	Block Condition	Select	=
	Lug Condition	Like new; Functioning	=
	Notch Condition	Select	
	Condition	Select	=
Magazine	Box Condition	Like new; Functioning	==
	Exterior Condition	Like new; Functioning	=
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
	Condition	Like new; Functioning	
Receiver	Bulged	False	
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	N/A
Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
a county rost	Condition	Like new; Functioning	=
Trigger	Pull	Select	3.5#
1115501	li uii		#נ. כן

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9517&Type=... 1/14/2014

Altered	False	SEALANT PRESANT
Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT 3, SWITH YOUR RETURN. This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information WITH YOUR RETURN.

Service Request Number | Serial Number | Description

M71914509

Model 770 RIFLE Caliber: 308

Destination:

11/21/2013 Date of Request:

Date Printed: 11/21/2013

SR00068490

Customer: EL DORADO PAWN 107 WEST HILLSBORO EL DORADO, AR 71730 US

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section Product Service #9517. jbi

Parts And Service Details Material

Type

Description

Qty Needed

Warranty

Disc Amount

∄M71914509

DEC 12 2013

could not dup, concern To restore confidence in Tifle will sup. T. A. check over + Myt AT N/K

uspapuly

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00


Est Sales Tax:


.00

Grand Total:

\$.00









ARS LABEL REQUEST FORM

DATE:	11/21/2013	Service Request #	SR00068490	
QUANTITY:	I	WEIGHT PER PACKAGE:	10 LBS	***
REQUESTED BY:	irvingjb	email address:	I will mail	
Business:				
Dusiliess.		Remington Service PO Box 700		
		Madison, NC 27025-0700 www.remington.com		

LABEL INFORMATION

	LADEL INI UNIVIATION
MAIL LABEL TO:	EL DORADO PAWN 107 WEST HILLSBORO EL DORADO, AR 71730 US SR00068490 Email:
RETURN ITEM TO:	ILN Arms Services



	4XX596 NOV 21, 2 SVC GNDCOM TRACKING# 1Z4XX5969065 REF 1:SR00068490 REF 2:	2013 ACT W 5600198	ALL T 10.0	. CURR USD LBS		1 0F 1	
	HANDLING CHARGE 0.00 SINGLE—PIECE PUB RATE DV 0.00	. 411114-	3: 0.00 0.00	AS Sc	T/P US 0.50 0.00	iD	
ATTN: Product Service	DC 0.00 AH 0.00 TOT PUB CHG 11.68	nn	0.00	SF HANDLING			