PM

Remington Arms Co., Inc. Product Service Legal Case #:9032

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete

315163 7/10/2013 7/15/2013 7/15/2013

Customer Information

Type Business First Name Last Name Street Zip Age Contact

336 Wekiva Park Dr. Incident Robert McDonald Sanford FL 32771

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ы

Sent in for Evaluation PD Cause:4063

Unknown Concern: 1007 Fired on Safe Release

S FSR \mathbf{C}

Consumer states will at times fire when safety removed. Not consistent, but one out of every 10 times.

Firearm Information

Mfg. Model/Ga. SKU **DOM** Type Serial Bbl. 3/14/2007 6:32:02

71360440 AB Remington CF/BA 770/243 WIN 85630

Date Original Where Purchased Accessories Purchased Owner

WAL-MART STORE **SCOPE** U **BASE** 0899

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/770/CF/BA

Reim. Cash Cash Reimbursement Settlement Release of Claims Settlement Release Date Date Date APV APV

Per Ilion, repair

at no charge

Repair/Replacement Repair/Replacement

Cost Date

\$41

7/16/13: Per Ilion, Trigger is not returning properly under sear.Replace TPA, check over and test at no charge.jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9032&Type=... 7/17/2013

Examination	Exam Date	}	7/15/2013
	Product Type	1	RF
	Action Type]	A
	Assigned To]	S.NICHOLS
Cause	4063	Sent in for Evaluation	TRIGGER IS NOT RETURNING UNDER SEAR PROPERLY
	Description]	22" 243 WIN
	Date Code]	AB
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Not Functioning	MARS,SCRATCHES
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	7
	Durged	<u> </u>	<u> </u>

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9032&Type=... 7/17/2013

	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIGGER IS NOT RETURNING PROPERLY UNDER SEAR
	Puli	Select	1.5#
	Altered	False	SEALANT INCONCLUSIVE DOES NOT APPEAR ADJUSTED
	Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT VITH YOUR RETURN.

Service Request Number SR00053868

Serial Number / Description

71360440

Model 770 RIFLE Caliber: 243

Customer:

ROBERT MCDONALD 336 WEKIVA PARK DR. SANFORD, FL 32771 US

Email:

05/29/2013 Date of Request:

Date

Printed: 05/29/2013

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

50

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

consumer states will at times fire when safety removed. Not consistent, but one out of every 10 tim es or so.

Parts And Service Details

Material

Type

Description

Qty Needed

Ų

Warranty

Disc Amount Price

TRIG. 15 NOT RETURNI no PROPREPLY . Und. Sepn. Pap. TPH, check ovent TOST AT N/C

731012 #

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







