Page 1 of 2 PrintDisplay

> Remington Arms Co., Inc. Product Service

Legal Case #:8664 Case Information Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit 2/28/2013 2/27/2013 2/28/2013 302186 **Customer Information** City State Zip Age Type Business First Name Last Name Street Contact H 503-449-3651 Warnicke 30592 Cottage Grove Lorane Rd Cottage Grove OR 97424 Incident E bwarnicke@gmail.com Incident Information Codes Repair Est. Medical Treatment **Medical Status** Claims Pl PD Cause:4015 Improper Maintenance Unknown S Fired 2 times with delay Concern: 1023 Delayed Firing - Firearms 3/4/13 Customer states the rifle has fired two times after trigger was pulled several seconds later when he touched the bolt handle.cm ΡĪ PD Cause:4022 12-20 Burst Unknown S Concern: 1023 Delayed Firing - Firearms C Firearm Information Model/Ga. SKU Serial Bbl. DOM Type Remington CF/BA 770/3006 SPRG 85633 M71835783 WG 8/29/2012 6:11:37 AM **Date Purchased** Where Purchased Accessories **Original Owner WAL-MART STORE 2320** SCOPE BASE U CONCERN: DELAYED FIRING Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/770/CF/BA Reim. Date Cash Date Cash Release of Claims Release Date Reimbursement Settlement Settlement APV APV Per Ilion, replace TPA, clean and test at no charge Repair/Replacement Repair/Replacement Cost Date 41.15 3/4/2013 3/4/13 Per Ilion, various kinds of debris found in and around the trigger assm. As a gesture of goodwill, replace TPA, clean and test at no charge.cm Examination[Remington/CF/BA]

гагі	Sub-rart	Coue	Continent
Examination	Examiner		B.TRAVIS
	Exam Date		2/28/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	VARIOUS KINDS OF DEBRIS WAS IN AND AROUND TRIGGER ASSEMBLY
	Description		22" 3006 SPRG
		1	

PrintDisplay Page 2 of 2

İ	Date Code		WG
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		.
	Muzzle/Crown Condition	Slightly Wom; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	_i	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	6#
	Altered	False	SEALANT INDETERMINATE
	Sub-Assembly	Other Remington]









