

Remington Arms Co., Inc.
Product Service
Legal Case #:8501

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
297410	1/18/2013	1/21/2013	1/21/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	3 M Tackle	---	3 M Tackle	1879 Main Street	Chireno	TX	75937		W 936-569-4422 E mjm56@netdot.com
Incident		Mike	Mettauer	PO Box 179	Chireno	TX	75937		H 936-569-4422

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

SR# 40479 - Service Request Section: Fired when safety taken off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	29717	S6283679	EP	10/26/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	BONITZ BROTHERS		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

1/22/13: Per Ilion - TA set screws altered, trigger not returning properly. Con offer to replace TA, clean & test at 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/21/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 3006 SPRG SS
	Date Code		EP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED SEALANT REMOVED
	Sub-Assembly	M/700 Non-Bolt Lock	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700 F:336-348-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

24"
EP10/95
3#
012

Service Request Number SR00040479	Serial Number / Description S6283679 Model 700S RIFLE	Date of Request: 01-04-2013 Date Printed: 01-04-2013
Customer: S M TACKLE 1879 MAIN STREET CHIRENO, TX 75937 US	Destination: Arms Services 14 Hoefler Ave Hick, NY 13357 US	
Email: mjn56@netnet.com		
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.		
Reason For Return M295 - EVALUATE AND REPAIR SAFETY INSP.		
Service Request Section fired when safety taken off		

Serial Number:

S6283679

Model: 700



RE00297410

Qty Needed	Warranty	Price	Disc	Amount
------------	----------	-------	------	--------

RECEIVED
JAN 22 2013

BY:

T.A. set screws & turned, trigger
not set properly. cannot
to up. Port, clean + test at
1/2 normal work.

Q

Mike Mettner

P.O. Box 179

Chireno, TX 75937

936-569-4422

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00







