

Remington Arms Co., Inc.
Product Service
Legal Case #:8406

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
293577	12/19/2012	1/2/2013	1/2/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bain & Davis Sporting Goods	Bain & Davis Sp	307 East Valley Blvd	San Gabriel	CA	91776			W 626-573-4241

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fires when bolt is closed	Concern:1008 Fired on Bolt Closing		
C				

1/10/13 Per note with rifle, goes off when bolt is closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	6321683	AT	3/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner			
	OLYMPIC WHLSE LOS ANG CAL	TWO PIECE BASE,SLING	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM program price.						
	Repair/Replacement Cost	Repair/Replacement Date				
	44.04	1/10/2013				

1/10/13 Per Ilion, trigger assm has a dried and sticky lube residue causing parts to bind and work sluggish. Replace TPA, clean and test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/2/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		AT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	SLUGGISH
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DRIED,STICKY LUBE RESIDUE PARTS BIND AND SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	10+#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,SLING



307 East Valley Blvd.
San Gabriel, CA 91776-3522
(626) 573-4241
(323) 283-7449

22"
AT 3/70
10+ #

8406

Customer's		Order No. _____		Date _____		20	
Name <u>KEMINGTON</u>							
Address _____							
Phone: _____							
SOLD BY	CASH	C.O.D.	CHARGE	ON ACCT.	MOSE RETD.	PAID OUT	LAYAWAY
QUAN.	DESCRIPTION					PRICE	AMOUNT
700	# 6321683						
	TRIGGER & SALTY						
	REAL						
	GOES OFF						
	When Bolt						
	IS CLOSED						
	w/ PASEL						
	A SLING						
All claims and returned goods MUST be accompanied by this bill.						TAX	
Received By <u>PAS</u>						TOTAL	

RECEIVED
JAN 03 2013

BY: _____

Serial Number:

6321683

Model: 700



RE00293577

T.A. has a dried + sticky (like
residue) causing parts to bind
& work sluggish. Replace TPA,
clean + test fire under BCP
for \$ 20.00 + shipping

Q





