

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8657

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 301855 | 2/25/2013   | 2/26/2013       | 2/26/2013   |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street          | City   | State | Zip   | Age | Contact                                     |
|----------|----------|------------|-----------|-----------------|--------|-------|-------|-----|---------------------------------------------|
| Incident |          | Daniel     | Beal      | 10738 Warner Rd | Darien | NY    | 14040 |     | H 716-474-1375<br>E dnuctoy@frontiernet.net |

## Incident Information

| Claims | Codes                                    | Repair Est.                | Medical Treatment                                          | Medical Status |
|--------|------------------------------------------|----------------------------|------------------------------------------------------------|----------------|
| PI     |                                          |                            |                                                            |                |
| PD     |                                          |                            |                                                            |                |
| S      | Discharged when moving from safe to fire | Cause:4006<br>Concern:1007 | Altered Adjustments or Components<br>Fired on Safe Release | Unknown        |
| C      |                                          |                            |                                                            |                |

3/3/13 Per note on SR, discharged when moving from safe to fire.cm

## Firearm Information

| Mfg.           | Type                          | Model/Ga.   | SKU            | Serial  | Bbl. | DOM      |
|----------------|-------------------------------|-------------|----------------|---------|------|----------|
| Remington      | CF/BA                         | 700/6MM REM | n/a            | 6328906 | KT   | 5/1/1970 |
| Date Purchased | Where Purchased               | Accessories | Original Owner |         |      |          |
|                | MONTANA HDWE GREAT FALLS MONT |             | U              |         |      |          |

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement                                        | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---------------------------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Replace TPA, clean and test at BLSM program price |                         |                         |               |                 |                |               |
|                                                   | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                                   | 29.04                   | 3/1/2013                |               |                 |                |               |

3/1/13 Per Ilion, trigger assm dirty and set screws altered. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

| Part        | Sub-Part               | Code                              | Comment        |
|-------------|------------------------|-----------------------------------|----------------|
| Examination | Examiner               |                                   | B.TRAVIS       |
|             | Exam Date              |                                   | 2/26/2013      |
|             | Product Type           |                                   | RF             |
|             | Action Type            |                                   | A              |
|             | Assigned To            |                                   | S.NICHOLS      |
| Cause       | 4006                   | Altered Adjustments or Components |                |
| Barrel      | Description            |                                   | 24" 6MM REM HB |
|             | Date Code              |                                   | KT             |
|             | Bore Plugged           | False                             |                |
|             | Bulged                 | False                             |                |
|             | Fired                  | False                             |                |
|             | Fired while Obstructed |                                   |                |

|              |                        |                                |                                            |
|--------------|------------------------|--------------------------------|--------------------------------------------|
|              | Muzzle/Crown Condition | Slightly Worn; Functioning     |                                            |
| Bolt         | Firing Pin             | Slightly Worn; Functioning     |                                            |
|              | Shroud                 | Slightly Worn; Functioning     |                                            |
|              | Face                   | Slightly Worn; Functioning     |                                            |
|              | Handle                 | Slightly Worn; Functioning     |                                            |
|              | Stop                   | Slightly Worn; Functioning     |                                            |
| Extractor    | Condition              | Slightly Worn; Functioning     |                                            |
|              | Cut Condition          | Slightly Worn; Functioning     |                                            |
|              | Ext/Eject Test         | False                          |                                            |
| Locking      | Block Condition        | ---Select---                   |                                            |
|              | Lug Condition          | Slightly Worn; Functioning     |                                            |
|              | Notch Condition        | ---Select---                   |                                            |
| Overall      | Exterior Condition     | Slightly Worn; Functioning     |                                            |
|              | Stock Condition        | Worn; Functioning              |                                            |
|              | Fore End Condition     | ---Select---                   |                                            |
| Receiver     | Condition              | Slightly Worn; Functioning     |                                            |
|              | Bulged                 | False                          |                                            |
| Safety       | Description            |                                | BOLT LOCK SAFETY                           |
|              | Function               | Like new; Functioning          |                                            |
| Sear         | Lift                   | ---Select---                   | .008                                       |
|              | Notch                  | Slightly Worn; Functioning     |                                            |
|              | Tests                  | Test Fired                     | False                                      |
| Feeding Test |                        | False                          |                                            |
| Trigger      | Condition              | Slightly Worn; Not Functioning | DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN |
|              | Pull                   | ---Select---                   | 2#                                         |
|              | Altered                | True                           | SET SCREWS ALTERED SEALANT MISSING         |
|              | Sub-Assembly           | M/700 Bolt Lock                |                                            |

PS 31404

Receipt Of Firearm(s) Delivered to the Plant for Repair  
Firearm Checked For Live Ammunition ☒

Driver's License ID# 3360 472 892

Delivery Date 2/22/13

Customer Name (Print) DANTEL BIAL

Employee (Y) (N)

Address 10735 WAPLE RD City DARTMOUTH

State NY Zip 14040 Phone Number (716) 474-1375

Manufacturer REMINGTON

Firearm Description Model 700 Cal./Ga. 6mm Rem

Serial Number 6328906

Stock/ Fore-end Condition - circle the description

(Excellent, Good, Fair, Poor, Fancy, Plain, Synthetic, Wood)

Comments on Stock/ Fore-end condition INFO TAPES TO STOCK

Metal Condition - circle the description

(Excellent, Good, Fair, Poor, Fancy, Plain Stainless Steel)

Comments on Metal condition

Barrel Type (VT. Rib; Plain; Deer; Stainless Steel ) Barrel length

List additional accessories: IE Scope, Sling, Gun case and description;

Customer request: SEE ATTACHED (BOLT LOCK SAFETY)

Return Process Return to Clark St. Ent. ☐ Return via UPS ☒

By signing this receipt the person delivering the firearm understands to be the only person to receive the firearm upon completion of repairs.

Signature Dante Bial Date 2/22/13

person delivering firearm

Signature A. W. [Signature] Date 2/22/13

security officer

Signature [Signature] Date 2/22/13

Arms Service / CSR

RECEIVED  
FEB 27 2013

BY:.....

Customer Pick Up Verification

I certify, I am the person whom delivered the above described firearm to the Remington Ilion plant for repair and may lawfully possess a firearm in New York State.

Signature \_\_\_\_\_ Date \_\_\_\_ / \_\_\_\_ / \_\_\_\_

person receiving firearm must be the same who delivered

Signature \_\_\_\_\_ Date \_\_\_\_ / \_\_\_\_ / \_\_\_\_

security officer or other witness returning the firearm

**Remington.**

Security Copy - White

Arm Service Copy - Yellow

Customer Copy - Pink

# Quotation

Remington Service

PO Box 700

Madison, NC 27025-0700

# Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

|                      |                                         |                                  |
|----------------------|-----------------------------------------|----------------------------------|
| <b>Repair Number</b> | <b>Serial Number / Description</b>      | <b>Date Received:</b>            |
| RF00301855           | 6328906                                 | 02/25/2013                       |
|                      | Model 700 Center Fire Caliber: 6 MM REM | <b>Estimate Date:</b> 02/26/2013 |
|                      |                                         | <b>Date Printed:</b> 03/01/2013  |

**Customer:**

DANIEL BEAL  
10378 WARNER ROAD  
DARIEN, NY 14040 US

**Return To:**

DANIEL BEAL  
10378 WARNER ROAD  
DARIEN, NY 14040 US

Please Circle One:

VISA MC DISCOVER Card No. \_\_\_\_\_ Exp. Date \_\_\_\_\_  
Open Account: R \_\_\_\_\_ PO Number: \_\_\_\_\_

Approval Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Daytime Phone: (\_\_\_\_) \_\_\_\_\_ Time to Call: \_\_\_\_\_

☐ If you desire any change, please use the reverse side for your comments and mark this box.

**Problems**

**Reported**

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION  
M240 - BOLT LOCK SAFETY MODIFICATION

**Found**

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION  
M238 - CLEAN & INSPECT (SAFETY PROGRAM ONLY)  
M240 - BOLT LOCK SAFETY MODIFICATION

**Technician Comments**

trigger assembly dirty and set screws altered. replace trigger plate assembly, clean and test fire under bolt lock program for \$20.00 + shipping

**ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)**

| Material | Type    | Description                            | Qty Needed | Warranty | Qty From Inv | Price | Disc | Amount |
|----------|---------|----------------------------------------|------------|----------|--------------|-------|------|--------|
| F305570B | Part    | X-MARK PRO 700 TRIG ASSB RH BLACK (OS) | 1          | Warranty | 1            | .00   | 0    | .00    |
| 4000114  | Service | GR-SHIPING & HANDLING (GUN REPAIR)     | 1          | Billable | 1            | 17.00 | 0    | 17.00  |
| 4000116  | Service | GR-LABOR                               | 20         | Billable | 20           | 1.00  | 0    | 20.00  |
| 4000119  | Service | GR-TEST                                | 1          | Warranty | 1            | .00   | 0    | .00    |

**Sub Total:** 37.00

**Est Sales Tax:** 2.59

**Grand Total:** \$39.59











