

Remington Arms Co., Inc.
Product Service
Legal Case #:8695

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
304144	3/11/2013	3/12/2013	3/12/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	BOUMSTYX FIREARMS	---	BOUMSTYX FIREAR	301 RALEIGH ST	NEWTON GROVE	NC	28366		E boustyxfirearms@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Dealer sent rifle in w/note: "Striker will fall approximately 8% of the time when safety is moved from 'safe' to 'fire' (bolt was cycled 100 times, set to safe, removed from safe to open bolt, striker dropped 8 times)". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6415135	LO	2/7/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	J C PENNY STATESVILLE NC		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM	Repair/Replacement Cost \$29	Repair/Replacement Date				

3/13/13: Per Ilion - TA & action, dirty & rusty. Parts work sluggish. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/12/2013
	Product Type		RF
	Action Type		A

	Assigned To	S.NICHOLS	
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		LO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	DIRTY,RUSTY
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Test Fired		False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY PARTS WORK SLUGGISH. WILL FOLLOW DOWN
	Pull	---Select---	5#
	Altered	False	SOME SEALANT MISSING SET SCREWS DO NOT APPEAR TO BE ADJUSTED
	Sub-Assembly	M/700 Bolt Lock	

Model Number: 700	Serial Number: A641535	
Name: Ronald Buchanan	Date of Purchase: UNK	
Address (no PO Boxes): 301 Raleigh Street		
City: Newton Groove	State: NC	Zip: 28366
Phone (Daytime): (910) 594-0342	Fax: (910) 594-0342	
E-mail Address: boumstyxfirearms@yahoo.com		
Please describe your problem: Striker will fall approximately 8% of the time when safety is moved from "Safe" to "Fire" (bolt was cycled 100 times, set to Safe, removed from Safe to open bolt, striker dropped 8 times). 312 characters left		
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.		
<p>WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> <p style="text-align: center;">Print Reset</p>		

72"
LOZ/77
5#
.007

8695

RECEIVED
MAR 13 2013

BY:

T.A. + Action, dirty + Rusty
 Parts work sluggish. rep.
 TPA, clean + situation
 BLP for 20 +

Q

Serial Number:

A6415135

Model: 700



RE00304144







