

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8721

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
305249	3/19/2013	3/20/2013	3/22/2013				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Dale & Loretta	Bundy	591 Hwy 93 S	Hamilton	MT	59840		H 406-544-9704

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Loretta Bundy sent a note in with rifle: "This gun has discharge 2 times when I released the safety. I quit using it along time ago but would like to be able to use it again". df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/6MM REM	n/a	6261617	WS	8/1/1969
Date Purchased	Where Purchased	Accessories	Original Owner			
	LAWTENCE PTLD ORE		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

3/22/13: Per Ilion - Could not duplicate concern. TA dirty & sticky, parts work sluggish. Replace TA, clean & test under BLM - quote. df  
3/22/13: I called Dale Bundy and he approved the quote & paid by credit card. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		3/20/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 6MM REM
	Date Code		WS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	LITE RUSTING UNDER STOCK
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, STICKY PARTS WORK SLUGGISH
	Pull	---Select---	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	

72"  
WS8/6C  
4.5#  
.006

I'm sending you my  
Remington 700 Model 872  
to be repaired.

This gun has Discharge  
2 times when I released  
the safety. I quit using  
it along time ago but would  
like to be able to use it  
again.

I talked to the Service  
Department and they said  
return it. They gave me  
a Service Request Number  
46963

Serial Number of my 6mm  
6261617 Model 700

Loretta Bundy  
591 Hwy 93 S  
Hamilton MT  
59840

You can talk to my husband  
DALE BUNDY 406 544-9704  
Thank you Very Much -  
Loretta Bundy

RECEIVED  
MAR 22 2013

BY:.....

Serial  
Number:

6261617

Model: 700



RE00305249

could not dup. concern  
T.A. dirty & sticky parts  
work sluggish. M. T.P.A.  
clean & test und. DCP  
for 20 r

4







