Remington Arms Co., Inc. Product Service Legal Case #:9074

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete

316457 7/26/2013 7/29/2013 7/29/2013

Customer Information

Street Type Business First Name Last Name City State Zip Age Contact

Carlton Guns HC 72 Box 412 Jasper AR 72641 Reporter Carlton Guns W 870-446-2180

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4015 Improper Maintenance

Unknown

C

S FSR

Service Request# 56265 - Dealer wrote a note: "My customer said that this gun fired when he pushed the safety off. (The safety and trigger don't seem right)". df

Firearm Information

Mfg.

Type

Concern: 1007 Fired on Safe Release

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA Where Purchased 700/270 WIN Accessories

25771 **Original Owner**  B6739404 WF 8/1/1985

**Date Purchased** 

K MART ENTERPRISES 66044 TWO PIECE BASE

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Date Reimbursement Date Settlement APV APV

Per Ilion -Quote to repair

> Repair/Replacement Repair/Replacement Cost Date

\$29

7/30/13: Per Ilion - TA very dirty & sticky causing parts to bind & work sluggish. Replace TA, clean & test - quote. df 7/31/13: I called dealer about quote but he only works during the day on Mon. & Fri. I will call back on Friday. df 8/2/13: Left message requesting customer call back about quote to repair. df 8/12/13: Consumer Service Dept. received quote w/payment & approval. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
		L	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9074&Type=... 10/1/2013

PrintDisplay Page 2 of 3

Examination	Examiner	1	B.TRAVIS
	Exam Date		7/29/2013
	Product Type		RF
	Action Type	]	A
	Assigned To	<u> </u> 	S.NICHOLS
	Assigned 10	] 	S.NICHOLS
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		WF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	<u></u>
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9074&Type=... 10/1/2013

Sear	Lift	Select	.018
	Notch	Slightly Worn; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY,STICKY PARTS BIND AND WORK SLUGGISH WILL FOLLOW DOWN
	Pull	Select	6#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

## Quotation

## Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS:

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Customer:  CARLTON GUN HC 72 BOX 412 JASPER, AR 72641 US  Please Circle One:  VISA MC DISCOVER Card No. Open Account: R PO Number:  Approval Signature: Daytime Phone:  If you desire any change, please use the reverse side for your comments and mark this box.  Problems Reported  Return To:  CARLTON GUN HC 72 BOX 412 JASPER, AR 72641 US  Exp.Date  Date:  Date:  Problems Found	
VISA MC DISCOVER Card No Exp.Date  Open Account: R PO Number:  Approval Signature: Date:	
Open Account: R PO Number:  Approval Signature: Date:  Date: Daytime Phone: Time to Call:  If you desire any change, please use the reverse side for your comments and mark this box.	
Approval Signature: Date:	·
Daytime Phone: Time to Call: If you desire any change, please use the reverse side for your comments and mark this box.	·
Daytime Phone: Time to Call: If you desire any change, please use the reverse side for your comments and mark this box.	·
If you desire any change, please use the reverse side for your comments and mark this box.  Problems  Found	CTION
Problems.  Found	CTION
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M127 - TRIGGER PULL IS OUT OF FACTORY SPECS  M123 - FORWARD TO PRODUCT SERVICE FOR INSPEC	
trigger assembly very dirty and sticky causing parts to bind and work sluggish, replace trigger assembly, clean and test fire at 1/2 normal cos	it.
ESTIMATE (note: C.O.D./Shipping and Handling Charges are NOT Included in this Quote.)  Material Type Description Qty Warranty Qty Price Disc Needed From Inv	Amount
F305570B Part X-MARK PRO 700 TRIG ASSB RH BLACK (OS) 1 Warranty 1 .00 0	.00
4000114 Service GR-SHIPPING & HANDLING (GUN REPAIR) 1 Billable 1 17.00 0	17.00
4000116 Service GR-LABOR 20 Billable 20 1.00 0	20.00
4000119 Service GR-TEST 1 Warranty 1 .00 0	.00
Sub Total: Est Sales Tax:	37.00 1.71

9074

## **CARLTON GUNS**

22" WF8/85 UF8/85

HC 72 BOX 412, JASPER AR. 72641

PHONE-870-446-2180

50# 56265

**REPAIRS NEEDED:** QRETURN TO: CARLTON GUNS—HC 72 BOX 412 JASPER, AR. 72641

BY: ....







