Remington Arms Co., Inc. Product Service Legal Case #:8439

Case Information

RE# Date Opened Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete 294952 1/4/2013 1/7/2013 1/7/2013

Customer Information

Business First Name Last Name Street State Zip Contact Type 381 NE Village Squire Ave. Crites Gresham OR 97030 H 503-314-6940 Incident Fred Unit 7

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause: 4038 Could Not Duplicate Concern S FSR

Unknown Concern:1007 Fired on Safe Release

C

SR# 38675 - Service Request Section: Gun is going off when going from safe to fire. df

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type Remington CF/BA 700/7MM REM MA n/a A6449904 KO 5/3/1977 Original Date Where Purchased Accessories

Purchased Owner HARRIS & STROH HAYWARD TWO PIECE BASE, BOTTOM HALF

U CA RINGS

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Reimbursement Settlement Release of Claims Release Date APV Settlement APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Repair/Replacement Date Cost

1/9/13: Per Ilion - Could not duplicate concern. TA dirty & rusty. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/7/2013
	Product Type		RF
	Action Type		Α
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	IMPROPER MAINTENANCE
Barrel	Description		24" 7MM REM MAG
	Date Code		КО
	Bore Plugged	False	
	Bulged	False]
	Fired	False]
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8439&Type=Case

1/15/2013

1		i	1
	<u> </u>	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning]
Locking	Ext/Eject Test	False]
	Block Condition	Select]
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Functioning]
Overall	Stock Condition	Worn; Functioning	MARS,DENTS,SCRATCHES
Receiver	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False]
C-C	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.005
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	lests	False	
	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
Tuiana	Pull	Select	4#
Trigger	Altered	False	SEALANT REMOVED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, BOTTOM HALF RINGS

Service Request

Remington Service PO Box 700



Date of Request:

12/14/2012

Printed: 12/14/2012

YH

.00

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

405/ This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number | Serial Number | Description

SR00038675

A6449904 Model 700

Customer: FRED CRITES

381 NORTH EAST VILLAGE SQUIRE AVE UNIT 7

GRESHAM, OR 97030 US

Email:

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

M295 - EVALUATE AND REPAIR/SAFETY INSP.

Service Request Section

GUN IS GOING OFF WHEN GOING FROM SAFE TO FIRE.

A6449904

Model:

Qty Warranty

Price Disc Amount

could not dup concern. Tradicty + Rusty. Mp.
TRA CLEAT TOST WAREN
BCP RON \$. 20. +

Q

BY:

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







