

Remington Arms Co., Inc.
Product Service
Legal Case #:8568

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
299030	2/1/2013	2/4/2013	2/4/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jerome	Davis Sr	905 Dunridge Dr.	Birmingham	AL	35215		H 205-201-4933

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Mr. Davis sent rifle in w/repair form. He stated he pushed safety off and gun fired. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	B6223953	WH	8/1/1987
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair @ 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date

2/5/13: Per Ilion - Could not duplicate concern. TA dirty & rusty, parts bind & work sluggish. Can offer to replace TA, clean & test at 1/2 normal cost. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/4/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		WH
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	METAL RUSTY,DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.014
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	RUSTY,DIRTY
	Pull	---Select---	5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

8568

Model Number: 700 BDL		Serial Number: B6223953	
Name: Jerome Davis Sr.		Date of Purchase: August 15, 1988	
Address (no PO Boxes): 905 Dunridge Drive 8568			
City: Birmingham		State: AL	Zip: 35215
Phone (Daytime): (205) 201-4933		Fax:	
E-mail Address:			
Please describe your problem: Pushed safety off and gun fired.			
<div style="text-align: right;"> RECEIVED FEB 05 2013 BY: _____ </div>			
500 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			

 22"
 WH 8/8
 5#
 .014

Serial Number:

B6223953

Model: 700



RE00299030

OR SPENT SHELLS IN YOUR
 WITH THE FIREARM. THIS IS A
 F YOU FEEL YOU MUST SEND
 THEM IN A SEPARATE PACKAGE AND
 H ZIP CODE), TELEPHONE AND
 F YOUR FIREARM.

or firearm before sending it.
 to prevent further damage in shipping

- firearm box. (Note: Original boxes may not be returned.)
- Remove all accessories from your firearm to prevent loss or damage.
 - Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

could not sup. concern.
 T.A. dirty + rusty parts
 Binds work sluggish.
 can't open to load. TPA c/c row
 + TEST AT 1/2 normal cost.

Q







