

Remington Arms Co., Inc.
Product Service
Legal Case #:8565

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
299029	2/1/2013	2/4/2013	2/4/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jerome	Davis Sr.	905 Dunridge Dr.	Birmingham	AL	35215		H 205-201-4933

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

Mr. Davis sent rifle in with our repair form. He stated the rifle fired when he chambered another round. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/3006 SPRG	27478	E6541570	AT	3/12/1999
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACADEMY CORP	SCOPE BASE,BOTTOM HALF RINGS	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

2/5/13: Per Ilion - Could not duplicate concern. Can offer to replace TA, clean & test at 1/2 normal cost & to restore confidence in rifle - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/4/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		AT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	SOME LITE RUSTING ON BBL
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,BOTTOM HALF RINGS

8565

72"
AT 3/9
5.5#
.013

Model Number: 700		Serial Number: E6541570	
Name: Jerome Davis SR		Date of Purchase: July 30, 1999	
Address (no PO Boxes): 905 Dunridge Drive 8565			
City: Birmingham	State: AL	Zip: 35215	
Phone (Daytime): (205) 201-4933		Fax:	
E-mail Address:			
Please describe your problem: Fire rifle when I chambered another round it fire on its own.			
RECEIVED FEB 05 2013			
500 characters left		BY: _____	
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			

Serial Number:

E6541570

Model: 700



RE00299029

OR SPENT SHELLS IN YOUR
WITH THE FIREARM. THIS IS A
IF YOU FEEL YOU MUST SEND
THEM IN A SEPARATE PACKAGE AND
(ZIP CODE), TELEPHONE AND
YOUR FIREARM.

firearm before sending it.
to prevent further damage in shipping

and handling. Preferably, ship in a
firearm box. (Note: Original boxes may not be returned.)
:: Remove all accessories from your firearm to prevent loss or damage.
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is
not responsible for damage or loss
during shipment, so you may elect to purchase insurance from your
carrier.

could not dup. concern,
can offer to rep. rpa, clean
+ test AT 1/2 normal cost to
restore confidence in rifle

Q





