Remington Arms Co., Inc. Product Service Legal Case #:9452

			Legal Case #:94					
Case Info	rmation		Legal Case #.94	J 24				
RE#	Date Opene	d Date Opened	d(PS) Date Clos	ed Incid	lent Date P	re Lit	Lit	Obsolete
327039	11/11/2013	_		13				
Customer	Information							
Туре	Business	First Las Name Nan	Street	City S	tate Zip Age	e	Con	tact
Reporter	Grand Rapids Police Dept	Capt. Gran Daniel Sa Rapide		Grand Rapids	MI 49503	F	616-4	56-3876 56-4354 e@grand- .mi.us
Incident I	nformation							
Claims		Codes		Repai]	Medical
Di				Est.	Treati	nent		Status
PI PD	Cause:4040	Other - Unspecifi Firearms	ied or Undetermined	-	Unkn	own		
S FSR C	Concern:10	07 Fired on Safe Re	lease					
shocked - discharge	he then placed d AGAIN!" jbi	the weapon on safe	fires when safety mo and cycled the bolt -					
	nformation	_						
Mfg	•	Туре	Model/Ga.	SKU	Serial	Bbl.		OOM
Reming	gton	CF/BA	700/308 WIN	25739	RR66054E	AH	3/3/20	13 4:15:01 PM
Date Purcha	Wh	ere Purchased	Accessories	Origina Owner	Ī			
COMOTT		AR WHOLESALE INC	SCOPE BASE,BIPOD	U				
CONCER	N: FSK							
		n - None Defined						
Settlemen	nt							
			Remington/700/CI	F/BA				
Settl	lement I	Release of Claims	Release Date	Reimbu	reement	ash ement	Rein Dat AP	e Date
trigger, o	n, replace check over fire at no arge						Ai	v ALV
	Re	epair/Replacement Cost	Repair/Replaceme Date	ent				

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9452&Type... 11/20/2013

\$50

PrintDisplay Page 2 of 3

11/13/13: Per Ilion, "trigger and connector not returning under sear. Replace trigger assembly, check over and test fire at no charge." jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	Ī	11/12/2013
Examination	Product Type		RF
	Action Type	1	A
	Assigned To]	S.NICHOLS
Cause	4040	Other - Unspecified or Undetermined - Firearms	
	Description]	20" 308 WIN FL HB
	Date Code		АН
	Bore Plugged	False	
 -	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
:	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Like new; Functioning	
l i	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9452&Type... 11/20/2013

	Bulged	False	}
Cafata.	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG/CONNECTOR NOT RETURNING UNDER SEAR. HAVE TO HOLD TRIG FORWARD TO CONNECT
T-:	Pull	Select	2.5#
Trigger	Altered	False	SEALANT PRESANT ON SEAR ENGAGEMENT SCREW.INCONCLUSIVE ON OVERTRAVEL SCREW
	Sub-Assembly	M/700 Non-Bolt Lock	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

20 "

Service Request Number | Serial Number / Description

SR00065611

RR66054B

Model 700 RIFLE Caliber: 308

GRAND RAPIDS POLICE DEPT

CAPT. DANIEL SAVAGE

1 MONROE CENTER NW GRAND RAPIDS, MI 49503 US

Email: dsavage@grand-rapids.mi.us

Destination:

Date of Request: 10/28/2013

Date Printed: 10/28/2013

Arms Services

14 Hoefler Ave

Ilion, NY 13357 US

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

fires when safety removed

d - he then placed the weapon on safe and cycled the bolt - he moved the safety again forward and the expectations again forward and the expectations again for the discharged - he was more than shocke

Parts And Service Details Material

Des cription

Qtv Needed

Warranty

Price Disc Amount

20054B

Model: 700



M NOV 1 3 2013

Trig + connector Not pet. properly 4 Test Line At 14/2

WARRANTY

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

PS 32269









