PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. **Product Service** Legal Case #:9275

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 323243 10/7/2013 10/8/2013 10/8/2013

Customer Information

First **Last Name** City State Zip Age Type **Business** Street Contact Name

5378 State Gun Works of Central Gun Works H 315-271-Reporter Verona NY 13478 Route 31 New York of Ce 8173

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Unknown Concern: 1028 Fired With Safe ON S FSO

C

Per Remington Firearm Receipt Form, "Not safe. Fires w/safe on." jbi

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type

700/7MM REM CF/BA Remington 25815 C6475651 XJ 12/6/1989 MA

Date Original Where Purchased Accessories Purchased Owner

OUTDOOR SPORTS HQ. INC., TWO PIECE BASE U #6

CONCERN: FSO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Reimbursement Settlement Settlement Release of Claims Release Date Date Date APV

Offer to replace trigger assembly, check over, and test at 50% discount

> Repair/Replacement Repair/Replacement Date

10/10/13: Per Ilion, "could not duplicate concern. Can offer to replace trigger assembly, check over and test fire to restore confidence in rifle at 1/2 normal cost." jbi 10/11/13: I called and spoke to Aaron with Gun Works, he approved repair. Paid with R acct. jbi

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9275&Type... 10/11/2013

Page 2 of 2

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/8/2013
Examination	Product Type		RF
	Action Type		A
!	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG
	Date Code		XJ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Wom; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6919	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock]
Non-Remington Components	Description		TWO PIECE BASE

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9275&Type... 10/11/2013

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPEACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00323243	C6	C6475651					Date:	10/07/29 10/08/29 10/11/29	8/2013			
Customer: THE GUN WORKS OF CENTRAL NEW YORK 5378 STATE ROUTE 31 VERONA, NY 13478 US Return To: THE GUN WORKS OF 5378 STATE GUN WORKS OF 5378 STATE ROUTE 3 VERONA, NY 13478 US							NTRAL NE	W YOF	RK			
Please Circle One: VISA MC DISCOVER Card No. Open Account: RPO Number:					Exp.Date							
Approval Signatur Daytime Phone	re: :: ()		Time to	o Call:					i			
If you desire any change, please use the reverse side for your comments and mark this box. Problems Found M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION												
Could not duplicate concern.can offer to replace trigger assembly check over and test fire to restore confidence in rifle at 1/2 normal cost.												
Material	Type ES	TIMATE (note: C.O.D. Description	Shipping and Han	dling Charges a Qty Needed	warranty	ed in this Q Qty From Inv	uote.) · s · · Price	Disc	Amount			
F305572B 4000114 4000119	Part Service Service	700 X-MARK PRO TR GR-SHIPPING & HAN GR-TEST		CK (OS) 1	Billable Billable Billable	1 1 1	86.00 17.00 23.00	0	43.00 17.00 11.50			
						Est	Total: Sales Tax: and Total:		71.50 5.01 \$76.51			

Driver's License ID# Delivery Date / 1 / 3 / /3 Employee (Y) (N) Customer Name (Print) Phone Number (State Manufacturer 700 Firearm Description Model Serial Number . Stock/ Fore-end Condition - circle the description (Excellent, Good, Fair, Poor, Fancy, Plain, Synthetic, Wood) Comments on Stock/ Fore-end condition _ Metal Condition - circle the description (Excellent, Good, Fair, Poor, Fancy, Plain Stainless Steel) Comments on Metal condition Barrel Type (VT. Rib; Plain; Deer; Stainless Steel) Barrel length List additional accessories: IE Scope, Sling, Gun case and description; Customer request: Return Process Return to Clark St. Ent. [] Return via UPS [] By signing this receipt the person delivering the firearm understands to be the only person to receive the firearm upon completion of repairs. could not dun concern. 1.13 CAN offen to Rep. T.A. Clack own & 7257 to restore confidence at Signature person delivering firearm Signature security officer Signature Arms Service / CSR k Up Verification BY: .. vered the above described firearm to the BC6475651 lawfully possess a firearm in New York State. Date the same who delivered Date eturning the firearm

Arm Service Copy - Yellow

Customer Copy - Pink

Security Copy - White

Receipt Of Firearm(s) Delivered to the Plant for Repair

Firearm Checked For Live Ammunition [X]

THE GUN WORKS OF CENTRAL NEW YORK 5378 STATE ROUTE 31 VERONA N.Y 1347

CONTACT PERSON FOR ESTIMATES OF REPAIR: AARON

cnygunworks@hotmail.com

ph: 315-363-7041 fax: 315-280-0841

OCT. 3, 2013

MODEL 700 SERIAL NO./REP# (6495651

CAL/GA.

290 372

REMINGTON ARMS ATTENTION REPAIRS:

X

PLEASE REPAIR AND RETURN

PLEASE PROVIDE ESTIMATE

Trigger Fired on Safe

PROBLEM REPORTED FOR REPAIR:







