

Remington Arms Co., Inc.
Product Service
Legal Case #:8708

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
304566	3/13/2013	3/15/2013	3/15/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Bradley Hively Sr Gunsmithing	---	Bradley Hively	2317 Shacktown Rd. PO Box 486	Yadkinville	NC	27055		W 336-961-3382

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

Gunsmith sent rifle in for a consumer. Consumer stated rifle fires when bolt closes. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/222 REM	n/a	6504834	XU	12/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	BADGER SHOOTR OWEN WISC		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

3/18/13: Per Ilion - TA set screws altered. Trigger not returning properly. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/15/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 222 REM
	Date Code		XU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	--Select--	.003
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG DOES NOT RETURN UNDER SEAR PROPERLY
	Pull	--Select--	2#
	Altered	True	SET SCREWS ALTERED SEALANT CHANGED
	Sub-Assembly	M/700 Bolt Lock	

3-8-13

ATTN:
SERVICE DEPT. #
SR 43498

NEEDS SAFE 8708
OPERATION REPAIRS
PERFORMED -
FIRES WHEN BOLT
CLOSES - PER
CUSTOMER
SN# 6504834 MOD.
700

THANKS
BRADLEY C. HIVELEY, SR.
BRAD

BRADLEY C. HIVELEY, SR.

GUNSMITHING

Specializing in black powder.
Complete restorations of antique and classic firearms.
NRA Certified Rifle & Pistol, NC Concealed-Carry Instructor
"The very atmosphere of firearms restrains evil interference
-they deserve a place of honor with all that's good."
-George Washington

2317 Shacktown Road
P.O. Box 486
Yadkinville, NC 27055

(336) 961-3382

RECEIVED
MAR 18 2013

BY:.....

Serial
Number:

6504834

Model: 700



RE00304566

T.A. set screws altered.
Trig. not returning properly.
Up. TRA, clean + Test Fire
and. BLP Ron & 20. + ship

Q

BRADLEY C. HIVELEY SR/ GUNSMITH 9 LBS
(336) 961-3382
PO BOX 486/ 2317 SHACKTOWN RD
YADKINVILLE NC 27055-7808

SHIP TO:

ARMS SERVICES SR 43498
REMINGTON ARMS CO.
14 HOFER AVE
ILION NY 13357-1816







