

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8743

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 305981 | 3/26/2013   | 3/1/2713        | 3/27/2013   |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street       | City      | State | Zip   | Age | Contact                                    |
|----------|----------|------------|-----------|--------------|-----------|-------|-------|-----|--------------------------------------------|
| Incident |          | Glen       | Kerns     | 7052 Ulan Rd | Indianola | OK    | 74442 |     | H 918-916-4551<br>E glen.kerns@hotmail.com |

## Incident Information

| Claims | Codes                               | Repair Est.                | Medical Treatment                                          | Medical Status |
|--------|-------------------------------------|----------------------------|------------------------------------------------------------|----------------|
| PI     |                                     |                            |                                                            |                |
| PD     |                                     |                            |                                                            |                |
| S      | Fired when he pushed safety forward | Cause:4006<br>Concern:1007 | Altered Adjustments or Components<br>Fired on Safe Release | Unknown        |
| C      |                                     |                            |                                                            |                |

4/1/13 Per note on SR, consumer states that the firearm went off when the consumer pushed the safety forward.cm

## Firearm Information

| Mfg.           | Type                        | Model/Ga.   | SKU            | Serial  | Bbl. | DOM      |
|----------------|-----------------------------|-------------|----------------|---------|------|----------|
| Remington      | CF/BA                       | 700/270 WIN | n/a            | 6558014 | KW   | 5/1/1972 |
| Date Purchased | Where Purchased             | Accessories | Original Owner |         |      |          |
|                | K MART ENTER ROYAL OAK MICH | SCOPE BASE  | U              |         |      |          |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement                                                   | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|--------------------------------------------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Per Ilion, replace TPA, clean and test at BLSM program price |                         |                         |               |                 |                |               |
|                                                              | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|                                                              | 29.04                   | 4/1/2013                |               |                 |                |               |

4/1/13 Per Ilion, trigger assm dirty and set screws altered. Replace TPA, clean and test at BLSM program price.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                              | Comment              |
|-------------|--------------|-----------------------------------|----------------------|
| Examination | Examiner     |                                   | B.TRAVIS             |
|             | Exam Date    |                                   | 3/27/2013            |
|             | Product Type |                                   | RF                   |
|             | Action Type  |                                   | A                    |
|             | Assigned To  |                                   | S.NICHOLS            |
| Cause       | 4006         | Altered Adjustments or Components | IMPROPER MAINTENANCE |
| Barrel      | Description  |                                   | 22" 270 WIN          |
|             | Date Code    |                                   | KW                   |
|             | Bore Plugged | False                             |                      |
|             | Bulged       | False                             |                      |
|             | Fired        | False                             |                      |

|                          |                        |                                |                                                 |
|--------------------------|------------------------|--------------------------------|-------------------------------------------------|
|                          | Fired while Obstructed |                                |                                                 |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning     |                                                 |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning     |                                                 |
|                          | Shroud                 | Slightly Worn; Functioning     |                                                 |
|                          | Face                   | Slightly Worn; Functioning     |                                                 |
|                          | Handle                 | Slightly Worn; Functioning     |                                                 |
|                          | Stop                   | Slightly Worn; Not Functioning | BINDS                                           |
| Extractor                | Condition              | Slightly Worn; Functioning     |                                                 |
|                          | Cut Condition          | Slightly Worn; Functioning     |                                                 |
|                          | Ext/Eject Test         | False                          |                                                 |
| Locking                  | Block Condition        | ---Select---                   |                                                 |
|                          | Lug Condition          | Slightly Worn; Functioning     |                                                 |
|                          | Notch Condition        | ---Select---                   |                                                 |
| Overall                  | Exterior Condition     | Slightly Worn; Not Functioning |                                                 |
|                          | Stock Condition        | Slightly Worn; Functioning     |                                                 |
|                          | Fore End Condition     | ---Select---                   |                                                 |
| Receiver                 | Condition              | Slightly Worn; Functioning     |                                                 |
|                          | Bulged                 | False                          |                                                 |
| Safety                   | Description            |                                | BOLT LOCK SAFETY                                |
|                          | Function               | Like new; Functioning          |                                                 |
| Sear                     | Lift                   | ---Select---                   | .007                                            |
|                          | Notch                  | Slightly Worn; Functioning     |                                                 |
|                          | Tests                  | Test Fired                     | False                                           |
| Feeding Test             |                        | False                          |                                                 |
| Trigger                  | Condition              | Slightly Worn; Not Functioning | VERY DIRTY. TRIG NOT RETURNING WILL FOLLOW DOWN |
|                          | Pull                   | ---Select---                   | 6.5#                                            |
|                          | Altered                | True                           | SET SCREWS ALTERED FACTORY SEALANT MISSING      |
|                          | Sub-Assembly           | M/700 Bolt Lock                |                                                 |
| Non-Remington Components | Description            |                                | SCOPE BASE                                      |

frmREInquiry - Repair Inquiry

Repair Number: **RE00305981**

Serial: 6558014 Model 700 Center Fire Caliber: 270 WIN

Repairman:

Verify Repair

8743

Status: New 2/14/2013 9:52:57 AM

ADDRESS INFORMATION

Customer

Received from

Return To

Received from

Name: GLEN KERNS

Address 1: 7052 ULAN ROAD

Address 2:

PO Box:

City: INDIANOLA

State: OK

Zip Code: 74442

Country: US

GLEN KERNS

7052 ULAN ROAD

PO Box:

INDIANOLA

OK

Zip Code: 74442

Country: US

FFL:

01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 918 916 4551

Fax:

Email: glen.kerns@hotmail.com

Comments: ans sent

Received Condition

Good

Condition

Notes

CSR

Notes:

Consumer states that the firearm went off when the consumer pushed the safety forward. JJW

Accessories Received

| Code | Desc       | Qty |
|------|------------|-----|
| A007 | With Stud  | 2   |
| A016 | Scope Base | 1   |

Repair Search

T/A dirty + set screws in it.  
Ago: T/A, 6 AM + test used.  
Dec 8 on 20 +

Refresh

MAR 28 2013

Close

BY:

Serial Number:

6558014

Model: 700



RE00305981

WEDNESDAY, MAR 27 2013

Wednesday, Mar 27 2013

5:53 AM

22"  
KWS/72  
.007  
6.5#

Dean Sirs

3/15/13

this is the 700  
that has a safety problem.  
Please let me know if there

~~is a change.~~

is a change.

THANKS  
Glen Lenns

918-916-4551









