Remington Arms Co., Inc. Product Service Legal Case #:9009

Case Information Pre Lit Lit Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** 314172 6/25/2013 6/26/2013 6/26/2013 Customer Information Type Business First Name Last Name Street State Zip Age Contact H 313-580-5859 23541 Parke Lane Grosse Ile MI 48138 Incident William (Bill) Krauss E wdkjr@me.com Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown Concern: 1028 Fired With Safe ON S FSO Service Request# 37826 - Service Request Section: "Rifle discharged with safety on. No injury or property damage." Firearm Information Model/Ga. SKU Serial Bbl. DOM Mfg. Type CF/BA 700/300 WIN MA 25807 E6804603 CP 4/12/1995 Remington Date Original Where Purchased Accessories Purchased Owner **GANDER** TWO PIECE BASE, BOTTM HALF U MOUNTAIN INC RINGS, MUZZLE BRAKE #110 CONCERN:FSO Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV Per Ilion - Quote to repair @ 1/2 normal cost Repair/Replacement Repair/Replacement Cost Date 6/28/13: Per Ilion - Could not duplicate concern. TA dirty & light rusting. Can offer to replace TA, clean & test at 1/2 normal cost. df 7/1/13: I called customer. Left VM to call me concerning quote. df 7/17/13: Customer called Consumer Serv. Dept, apprvd & pd quote. df Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9009&Type=... 7/22/2013

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date	1	6/26/2013
Examination	Product Type	j	RF
	Action Type	Ī	A
	Assigned To	·	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		24" 300 WIN MAG
	Date Code]	СР
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select]
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD SAFETY
Safety		Like new;	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9009&Type=... 7/22/2013

		Functioning	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Functioning	DIRTY, LITE RUSTING
Trigger	Pull	Select	7#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,BOTTM HALF RINGS,MUZZLE BRAKE

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00314172		Serial Number / Description E6804603 Model 700 RIFLE Caliber: 300 WIN MAG				Estimate	te Received: 06/25/2013 timate Date: 06/26/2013 te Printed: 06/28/2013			
Customer: Return To: WILLIAM KRAUSS 23541 PARKE LANE GROSSE ILE, MI 48138 US RETURN TO: WILLIAM KRAUSS 23541 PARKE LANE GROSSE ILE, MI 48138 US					LANE	J S				
Please Circle One VISA MC Open Accoun	DISCO'	VER Card No PO Number:	***		Exp	.Date				
Approval Signature:										
If you desire any change, please use the reverse side for your comments and mark this box. Problems Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M568 - SAFETY BROKEN M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M124 - FORWARD TO PRODUCT SERVICE FOR INSPECTION										
Technician Comments could not duplicate concern.trigger assembly dirty and lightly rusted. can offer to replace trigger assembly, clean and test fire at 1/2 normal cost.										
		ESTIMATE (note: C.O.D./Shipping and Han	dling Ch	arges a	re NOT Include	ed in this Q	uote.)		_	
Material	Type	Description		Qty eded	Warranty	Qty From Inv	Price	Disc	Amount	
F305570B 4000114 4000119	Part Service Service	X-MARK PRO 700 TRIG ASSB RH BLA GR-SHIPPING & HANDLING (GUN REF GR-TEST		1 1 1	Billable Billable Billable	1 1 1	97.00 17.00 23.00	0	48.50 17.00 11.50	
	SCITIC	SK 1201		-	Billable	-	20.50			
							o Total: Sales Tax:		77.00 2.91	
						Gra	and Total:		\$79.91	

DO NOT USE This

(QUI)

Reministran is Related Request SR00037826

Mode #700 gm 8:26 AM EST

UNITHEUSED DISCHARGE P

10-25-18

24" CP 4/9 9#

3 Attachments, 186 KB

Please open the attached JPG files and follow their instructions for your Service Request SR00037826.

Service Request

Remington Service

Parts and Repairs: P:900-243-9700 F:336-548-7801

Madison, NC 27025-0700 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number | Serial Number | Description |
SR 00037826 | E6804603 | Model 700 RIFLE Caliber: 300

Date of Request: 12 07 2012
Date Printed: 12 07 2012

Customer: WILLIAM KRAUSS 25541 PARKE LANE GROSSE ILE, MI 48138 US Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email: wdkjr@me.com

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M568 - SAFETY BROKEN

DECEIVE

Service Request Section

Rifle discharged with safety on. No injury or property damage.

BY: ..

^體E6804603

Model: 700

RE00314172

Qty Warranty Needed Price Disc Amount

could not hip concern J. A. Linky + like wisting. CONOPER to mp TARCHAN + Trest At 1/2 MORNAI EOST.

9







