

Remington Arms Co., Inc.
Product Service
Legal Case #:8413

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
294124	12/26/2012	1/2/2013	1/2/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry M	Lavan Jr	1269 Shaffer Run Rd	Oil City	PA	16301		E mhmte@comcast.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired when safety was pushed off	Concern:1007 Fired on Safe Release		
C				

1/9/13 Per note on SR, the gun went off as he pushed safety off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	n/a	6502347	XU	12/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	FED FIREARMS CO OAKDALE PA	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.04	1/9/2013				

1/9/13 Per Ilion, could not duplicate concern. Trigger assm dirty, rusty. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/2/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		XU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	BUTT PLATE MISSING
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

XFINITY Connect

mhmtb@comcast.net

SR00038609_SR.jpg

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700

www.Remington.com

Parts and Repairs: P:800-243-9700 F:336-548-7801

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number SR00038609	Serial Number/Description 6502347 Model 700243	Date of Request: 12-14-2012 Date Printed: 12-14-2012																
Customer: LARRY MLAVAN, JR 1269 SHAFFER RUN RD OIL CITY, PA 16301 US	Destination: Arms Services 14 Hoefler Ave Bloom, NY 13337 US																	
Email: mhmtb@comcast.net	Email:																	
<p>Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.</p>																		
<p>Reason For Return M1240 - BOLT LOCK SAFETY MODIFICATION</p>																		
<p>Service Request Section PER CONSUMER, THE GUN WENT OFF AS HE PUSHED SAFETY OFF.</p>																		
<table border="1"> <thead> <tr> <th>Material</th> <th>Type</th> <th>Description</th> <th>Qty</th> <th>Warranty</th> <th>Price</th> <th>Disc</th> <th>Amount</th> </tr> </thead> <tbody> <tr> <td colspan="8"> <p>Serial Number: 6502347 Model: 700</p> <p>RE00294124</p> </td> </tr> </tbody> </table>			Material	Type	Description	Qty	Warranty	Price	Disc	Amount	<p>Serial Number: 6502347 Model: 700</p> <p>RE00294124</p>							
Material	Type	Description	Qty	Warranty	Price	Disc	Amount											
<p>Serial Number: 6502347 Model: 700</p> <p>RE00294124</p>																		
<p>THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the</p>																		
<p>Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00</p>																		

22"
x 12/71
4.5#
.008

RECEIVED
JAN 03 2013

BY:

could not disp concern
T.A. dirty, rusty. rep.
TW, clean & test and
BLP for H2O. +

SR00038609_SRcopy.jpg

<http://web.mail.comcast.net/h/viewimages?id=237600>

12/14/2012







