PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:8896

Case Information

Obsolete RE# Date Opened(PS) Date Closed **Incident Date** Pre Lit **Date Opened**

5/8/2013 5/9/2013 5/9/2013 310358

Type Business First Name Last Name Street City State Zip Age Contact

20885 S. Birchwood Loop Rd, Apt 2 Incident Luke Chugiak AK 99567 H 907-688-0414

Incident Information

Customer Information

Claims Codes Repair Est. Medical Treatment Medical Status

Ρł

PD Cause: 4006 Altered Adjustments or Components

Unknown

S Fired when opening bolt Concern:1020 Fired on Bolt Opening

5/13/13 Per note with rifle, rifle has misfired twice. Once when unloading gun with safety off and opening the bolt.cm

Firearm Information

Mfg. Model/Ga. SKU Type Remington CF/BA 700/308 WIN n/a

Date Purchased Where Purchased Accessories **Original Owner**

KALAMAZOO CO KALAMAZOO MCH SCOPE, RINGS, TWO PIECE BASE

Serial Bbl. DOM

6464066 DU 9/1/1971

CONCERN: FSR,FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Cash Settlement Release of Claims Reimbursement Release Date Settlement Date APV Date APV

Per Ilion, replace TPA, clean and test at BLSM program price

Repair/Replacement Repair/Replacement Cost Date

66.04 5/13/2013

5/13/13 Per Ilion, trigger assm dirty, sticky and rusty. Set screws altered. Replace TPA, clean and test at BLSM program price cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Datc		5/9/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		22" 308 WIN
	Date Code		טט
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		_
			7

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8896&Type=Case

5/13/2013

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	FINISH WEAR AND RUST
Overall	Stock Condition	Worn; Functioning	MARS,DENT,SCRATCHES. STOCK IS BEDDED FULL LENGTH OF BBL CHANEL HAD TO TAKE OFF SCOPE TO USE STOC
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Slightly Wom; Functioning	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY,RUSTY PARTS SLUGGISH WILL FOLLOW DOWN
	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED SEALANT MISSING
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE

4/19/13

8896

D) MISS Fries The latery

#1/ MISS fine & #2

SAFTY OFF & UNDADING

GUN = MIS FINE OPENING

BO 15.

MIKE LUKE

907-688-0414.

72" Du9/7. 300)

6464 Model:	4066	
[∥] Model:	700	
D	EWW3	1 クスロ

PECEIVE L MAY 1 0 2013						
N	MAY	1	0	2013		
_	v.					

	Custonica	Recei
me	MIKE LUKE	
s :	20885 S BIRCHWOOD LOOP ROAD APT 2	
s 2 :	PO Box:	CONTRACTOR OF THE STREET
ity:	CHUGIAK	**************************************
ite:	AK Zip Code: 99567 Country:	us

T. A. dirty, sticky + rusty. Set screws Alt. Rep. TOA, LLAN & TUST UND BLP CON ZU +







