PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:8476

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 296345 1/11/2013 1/14/2013 1/14/2013

Customer Information

Type Business First Name Last Name Street City Zip Contact Age 705 Grove Incident Mares Roswell NM 88201 E jimmymares@yahoo.com James

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Concern:1007 Fired on Safe Release S Fires when safety is taken off

Unknown

1/17/13 Per note on SR, fires when safety is taken off. Goes off by itself at random.cm

Firearm Information

SKU Mfg. Model/Ga. Bbl. DOM Type Serial 700/270 WIN Remington CF/BA B6274497 BB 1/5/1981 n/a

Date Purchased

Where Purchased

Accessories

Original Owner

EL PASO WHSLE LUBBOCK TX

Reimbursement

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Release Date

Cash

Settlement

Reim. Date Cash Date

APV

APV

Settlement Per Ilion, replace TPA, clean, test

at BLSM program price

Repair/Replacement Repair/Replacement

29.04

Release of Claims

1/17/2013

1/17/13 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/14/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		BB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8476&Type=Case

1/17/2013

I			
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Candition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking Overall	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tesis	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Parts and Repairs: P:\$00-243-9700/F:336-548-7801

www.remington.com

is document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This rmation will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE IS DOCUMENT WITH YOUR RETURN.

22" 8/1951

4.5

- D 11

nice Request Number

Serial Number / Description

00039627

B6274497

Model 5770

stomer: JAMÉS MARES 705 GROVE

ROSWELL, NM 89201 US

Destination:

Arms Services 14 Hoefler Ave

Rion, NY 13357 US

Email: jimmymares@yahoo.com

Email:

our request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be baired and returned. If not, you will be contacted with an estimate before work is performed.

eason For Return

240 - BOLT LOCK SAFETY MODIFICATION

rvice Request Section

RES WHEN SAFETY IS TAKEN OFF

by itself @ RANDOM.

irts And Service Details

terial

Type

Description

Qtr Needed

Warranty

Price

Disc Amount

12/27/2012

12/27/2012

Date of Request:

Date Printed:



BY:____

could next dup, concern.

J.A. don'ty a set & creus n/tend.

Apr TPA, cleans test und. BCP

Con 20. +

IIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:

.00 .00

Est Sales Tax: Grand Total:

\$.00







