PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:8666

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Obsolete 302279 2/27/2013 2/28/2013 2/28/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Mills 28041 Wilson Hollow Main St 13755 H 607-363-2482 Downsville NY Incident Charles

Incident Information

Repair Medical Medical Claims Codes Est. Treatment Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Concern: 1025 Unexplained Discharge - No Mention of Safety Position Unknown Went off while S

unloading

3/4/13 Per note on SR, firearm went off while the firearm was being unloaded.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. DOM Type A6204416 EZ 10/9/1975 700/270 WIN Remington CF/BA n/a

Date Original Where Purchased Accessories Purchased Owner

JERRYS SPORT CTR MONTDALE BOTTOM HALF OF REAR SEE THRU

U PA BASE

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Date Cash Date Settlement Release of Claims Release Date Reim bursement Settlement APV

Replace TPA, clean and test at

BLSM price

Repair/Replacement Repair/Replacement Cost Date

3/4/2013 29.04

3/4/13 Per Ilion, trigger assm very dirty and rusty. Could not duplicate concern. Replace TPA, clean and test at BLSM price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/28/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		EZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8666&Type=Case

3/4/2013

	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop .	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	
Overall	Stock Condition	Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.009
	Notch	Slightly Worn, Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY,RUSTY
	Pull	Select	6#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	



Estimate:Repair SFExpedite Repair Inquiry Scrifile Add Repair Repair Tools CSR Tools Reports Table Maintenance frmREInquiry - Repair Inquiry Serial: A5204416 Model 700 Center Fire Caliber: 270 Repairman: WIN Produced: 10/09/1975 SKU: 20000 Repair Number: RE00302279 Status: New 2/14/2013 10:28:07 AM Verify Repair **High Priority** 8666 ADDRESS INFORMATION Customer Received from Return To C Received from CHARLES MILLS CHARLES MILLS 28041 WILSON HOLLOW MAIN STREET 28041 WILSON HOLLOW MAIN STREET Address 1: Address 2: PO Box: PO Box: DOWNSVILLE City: DOWNSVILLE Country: US NY Zip Code: 13755 Country: US NY Zip Code: 13755 01011900 Contact / Condition | Problems | Estimate | History / Status | Shipping / Billing Contact Information Received Condition -Accessories Received Qtv Code Desc 607 363 2482 Phone: Good A007 With Stud Fax: Condition A016 Scope Base Notes Email: ars sent Comments: CSR Firearm went off while the firearm was being unloaded. Refresh Close Model: RE0030227 Yoursday Febras 1911LASRPR 11 3/33 4/4 Thursday, Feb 28 2013 3:33 AM











