Remington Arms Co., Inc.
Product Service

Legal Case #:9746

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 332169 12/27/2013 12/30/2013 12/30/2013

**Customer Information** 

Type Business First Name Street City State Zip Age Contact

Reporter Outdoorsman

Attn:
Jacob

Outdoorsman

Outdoorsman

Deauregard Ave

Angelo

TX 76901

H (325) 947-4871

E bhhunts@aol.com

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

ΡI

PD Cause: 4006 Altered Adjustments or

S FSR Cand Cause: 4006 Components Unknown
Concern: 1008 Fired on Bolt Closing

C

Per SR00071337 Service Request Section, "2006 gun = discharges while closeing bolt and moveing safety. no injuries and no damages." jbi

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/300 WIN MA
 27099
 G6554597
 LA
 2/17/2006 2:43:21 PM

Date
Purchased

Where Purchased Accessories

Original
Owner

BILL HICKS & CO TWO PIECE LTD BASE U

CONCERN: FIRES INVOLUNTARILY

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Settlement Release Date Reimbursement Release Date Rele

Per Ilion, replace trigger, check over, and test at 50% discount

Repair/Replacement Repair/Replacement

Cost Date

\$46

1/3/14: Per Ilion, "trigger assembly set screws altered. Trigger not returning properly. Can offer to replace trigger

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9746&Type=... 1/21/2014

PrintDisplay Page 2 of 3

assembly, check over and test fire at 1/2 cost." jbi 1/7/14: Dealer called into Consumer Service and approved quote with a credit card. jbi

## Examination[Remington/CF/BA]

Sub-Part	Code	Comment
Examiner		B.TRAVIS
Exam Date		12/30/2013
Product Type		RF
Action Type		A
Assigned To		S.NICHOLS
4006	Altered Adjustments or Components	
Description		26" 300 WIN MAG
Date Code		LA
Bore Plugged	False	
Bulged	False	
Fired	False	
Fired while Obstructed	•	
Muzzle/Crown Condition	Slightly Worn; Functioning	
Firing Pin	Slightly Worn; Functioning	
Shroud	Slightly Worn; Functioning	
Face	Slightly Worn; Functioning	
Handle	Slightly Worn; Functioning	
Stop	Slightly Worn; Functioning	
Condition	Slightly Worn; Functioning	
Cut Condition	Slightly Worn; Functioning	
Ext/Eject Test	False	
Block Condition	Select	
Lug Condition	Slightly Worn; Functioning	
Notch Condition	Select	
Exterior Condition	Slightly Worn; Not Functioning	
Stock Condition	Slightly Worn; Functioning	
Fore End Condition	Select	
Condition	Slightly Worn; Functioning	
Bulged	False	
Description		STANDARD SAFETY
Function	Like new; Functioning	
Lift	Select	.010
Notch	Slightly Worn; Functioning	
Tests	Test Fired	False
	Examiner Exam Date Product Type Action Type Assigned To  4006 Description Date Code Bore Plugged Bulged Fired Fired while Obstructed Muzzle/Crown Condition Firing Pin Shroud Face Handle Stop Condition Cut Condition Ext/Eject Test Block Condition Lug Condition Exterior Condition Exterior Condition Fore End Condition Condition Condition Fore End Condition Condition Condition Fore End Condition	Examiner  Exam Date  Product Type  Action Type  Assigned To  4006  Altered Adjustments or Components  Description  Date Code  Bore Plugged  False  Fired  False  Fired False  Fired While Obstructed  Muzzle/Crown Condition  Firing Pin Slightly Worn; Functioning  Shroud Slightly Worn; Functioning  Face Slightly Worn; Functioning  Stop Slightly Worn; Functioning  Stop Slightly Worn; Functioning  Condition Slightly Worn; Functioning  Stop Slightly Worn; Functioning  Condition Slightly Worn; Functioning  Cut Condition Slightly Worn; Functioning  Ext/Eject Test False  Block Condition Slightly Worn; Functioning  Exterior Condition Slightly Worn; Functioning  Stock Condition Slightly Worn; Functioning  Fore End Condition Slightly Worn; Functioning

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9746&Type=... 1/21/2014

Feeding Test		False			
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN		
	Pull	Select	2.5#		
	Altered	True	SET SCREWS ALTERED		
	Sub-Assembly	M/700 Non-Bolt Lock			

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9746&Type=... 1/21/2014

## Quotation

## Remington Service PO Box 700

Madison, NC 27025-0700

## Estimating Report

Parts and Repairs: P:(800) 243-9700/F:(336) 548-7801 www
All-PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

www.remington.com

Page: 1

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Remington disclaims all warranties concerning legality of a firearm's configuration under applicable state, county & local laws or regulations. Consumers are advised to check their local laws to determine whether certain firearm features are lawful.

					·········			
Customer: THE OUTDOORSMAN ATTN: JACOB 2231 WEST BEAUREGARD AVE SAN ANGELO, TX 76901 US				Item Return To: THE OUTDOORSMAN ATTN: JACOB 2231 WEST BEAUREGARD AVE SAN ANGELO, TX 76901 US				
	SAN AIN	0000, TX 10001 00	,		o, u v ru v	Jobo, IX	70201	
Please Circle C	)ne·			· <u> </u>				
VISA M		VER Card No		Ex	p.Date			
Ореп Ассо	unt: R	PO Number:					<del></del>	
					_ Date:			
Daytime Ph		) Time to Call						
<del></del>		nge, please use the reverse side for your comments and	mark this bo	x				
Repair Number	er	Serial Number / Description			Date Rec		12/27/20	
RE00332169		G6554597 Model 700 Center Fire Caliber: 300 WIN MAG			Estimate Date Pri		12/30/20 1/21/201	
		Problems			DATE		17217201	
Reported				, nn ma nn a	ni an		Nonno	
KUI4 - FUK	WARD IO	PRODUCT SERVICE FOR INSPECTION ROI	4 - FUKW/	ARD TO PRO	DUCI SEKV	ICE FOR I	NSPEC.	IION
trigger assemble at 1/2 cost	ly set screws	Technician Com altered trigger not returning properly. can offer to repl	ments ace trigger a	ssembly,check	over and tes	t fire		65 - 1
		ESTIMATE (note: C.O.D./Shipping and Handling	Charges are	e NOT Includ	led in this O	uote.)		
Material	Туре	Description	Qty	Warranty	Qty	Price		Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLACK (OS)	Needed 1	Billable	From Inv 1	97.00	50	48.50
4000114 4000119	Service Service	GR-SHIPPING & HANDLING (GUN REPAIR) GR-TEST	1 1	Billable Billable	1 1	17.00 23.00	0 50	17.00 11.50
4000119	Service	GR-1E31	1	Billable	1	23.00	30	11.50
		<i>:</i>						
						Total:		77.00
					Est	Sales Tax:		5.20
					Gra	nd Total:		\$82.20

WE DO FOR A LIVIN' - WHAT WE DO FO	IR FUN!	REPAIR	VOICE	 . · ,
AUTDOC 25MA	N	13	00	• •
ARCHERY · HUNTING · SAF			4746	· · ·
	9 • Fax 3	125.947.1571		
outdoorsman@zipnet.u	is • www	shopoutdoc	rsman.com	÷-
DATE IN TO FACTORY FROM FAC	TORY	PICK UP/S	HIP DATE	
NAME TELL COULD		HOME PHONE		
STREET 2 195 NA NA		WORK ?	224 15%	3
CITY OF FAMILIE		STATE	17/17/21P	
Katharyton - J. Blancolle	AL #165	54547	CALIGA	
Description of Problem		· · · · · · · · · · · · · · · · · · ·		
Fires einvoluntarily			<u> </u>	٠.
	4.			
				3.
List of Parts	Qty	Rate	Amount	
			_	
<b>2</b> G 6 5 5 4 5 9 7				
Model: 700				
A ESTRUM TRANSPORTED AND A MARK MARK MARK SUMMA COMMANDO		1.		20
RE00332169		ping		
NE00332107		To ping		
We appreciate your business!		<u>From</u> Tax		• •
EQUIPMENT RECEIVED WITH REPAIR	7			``; 
☐ CASE ☐ FACTORY BOX ☐ SCOPE ☐ AMMO # RDS ☐ SLING		Total		
OTHER	1			

26	, It
LA	2/6/
しみ	بان برن المدير
2	, SH
	10
,0	٠.

1	ZC.	E	I	WI	ااار <sub>ت</sub> ات <u>ت</u>
	JAN	0	3	₩ <u>1</u> 20,4	
DV.					

TM. Set SCRUS Alt. FRIG NOT PUT CANOFLEN to Rep. T.A cleckows t The ST AT 1/2 LOST

Q







