

Remington Arms Co., Inc.
Product Service
Legal Case #:8987

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
313301	6/12/2013	6/13/2013	6/13/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		James	Pappert	39754 Pebble Rd	Guilford	MO	64457		C 816-262-5069

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired when closing bolt Concern:1008 Fired on Bolt Closing			
C				

6/14/13 Per letter with rifle, James has given this rifle to his son, Dylan. He and his son shot their first whitetail with this rifle. Last Fall when his son loaded the gun and closed the bolt it fired. No one was hurt but it scared them.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	n/a	101278	CL	4/1/1964
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.04	6/14/2013				

6/14/13 Per Ilion, could not duplicate concern. Trigger assm dirty, sticky and set screws altered. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/13/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		20" 243 WIN
	Date Code		CL
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS, SCRATCHES
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Scar	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, STICKY
	Pull	---Select---	7#
	Altered	True	SCREWS ALTERED SEALANT MISSING
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington Model 700 Ser. # 101278

James Pappert

39754 Pebble Road

Guilford, MD 64457

cell 816-262-5069

8987

20"
CL4/44
7#
.006

Safety Modification Program
Service Request # SR00051073

2nd hand

this is my first rifle and my favorite. I shot my
first whitetail with this rifle. I have given this rifle
my son. He also shot his first whitetail with this
rifle. But last fall when my son loaded the gun and
cocked the bolt it fired. No one was hurt but it
scared both of us. Now he won't hunt with any
other rifle and I don't feel safe letting him use
his one anymore. Please make this rifle safe for
my son & hopefully my grandchildren will enjoy this rifle
too. I contacted Remington and they said to send
this rifle to you.

Thank You.

James Pappert

Dylan Pappert

RECEIVED
JUN 14 2013

BY:.....

first white tail.

101278

Model: 700



RE00313301

could not dup. concern
T.A. dirty, sticky & sets screws
A/S. Rtg. T.A. & check test
und. BCP Ron 20 +

Q







