Page 1 of 3

Remington Arms Co., Inc.
Product Service
Legal Case #:9156

Legal Case #:9156 Case Information Pre Lit Lit Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** 9/16/2013 9/17/2013 9/17/2013 321167 Customer Information Street City State Zip Age Contact **Business First Name Last Name** Type C 315-408-6675 Reporter Pete's Guns Attn: Pete Pete's Guns 251 State St. Carthage NY 13619 E gunguy39@yahoo.com Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause: 4006 Altered Adjustments or Components Unknown S FSR Concern:1007 Fired on Safe Release C 8/30/13: Dealer called in. He said consumer brought rifle to him & said about 2-3 weeks ago (no incident date available), the rifle had a FSR, no damage, no injury. df Firearm Information Model/Ga. SKU Serial Bbl. DOM Mfg. Type CF/BA 700/3006 SPRG n/a A6350621 DI 9/1/1976 Remington Date Original Where Purchased Accessories Owner Purchased **ROSKIN BROS MIDDLETOWN SCOPE** N NY **BASE, RINGS** CONCERN: FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Reim. Cash Cash Reimbursement Settlement Settlement Release of Claims Release Date Date Date APV Per Ilion - Ouote to repair under **BLM** Repair/Replacement Repair/Replacement Cost Date \$29 9/3/13: Mailed ARS, letter & SR paperwork to dealer. df 9/18/13: Per Ilion - TA dirty & set screws altered. Replace TA, check over & test under BLM - quote. df Examination[Remington/CF/BA] Part **Sub-Part** Code Comment

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9156&Type=... 9/26/2013

PrintDisplay Page 2 of 3

	Examiner	7	B.TRAVIS	
Examination	Exam Date		9/17/2013	
	Product Type	1	RF	
	Action Type	1	A	
	Assigned To	j	S.NICHOLS	
Cause	4006	Altered Adjustments or Components		
	Description		22" 3006 SPRG	
	Date Code	1	DI	
	Bore Plugged	False		
	Bulged	False	7	
Barrel	Fired	False	j	
	Fired while Obstructed			
	Muzzle/Crown Condition	Slightly Worn; Functioning		
	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning	1	
Bolt	Face	Slightly Worn; Functioning	<u> </u>	
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
	Condition	Slightly Worn; Functioning	1	
Extractor	Cut Condition	Slightly Worn; Functioning	Í	
	Ext/Eject Test	False	Ī	
	Block Condition	Select		
Locking	Lug Condition	Slightly Worn; Functioning	Ī	
-	Notch Condition	Select	4	
Overall	Exterior Condition	Slightly Worn; Not Functioning	=	
	Stock Condition	Slightly Worn; Functioning	Ī .	
	Fore End Condition	Select	Ħ	
- ·	Condition	Slightly Worn; Functioning	Ī	
Receiver	Bulged	False	Ī	
Safety	Description		BOLT LOCK SAFETY	
	Function	Like new; Functioning		
Sear	Lift	Select	.007	
	Notch	Slightly Worn; Functioning		
		Test Fired	False	
Feeding Test	Tests	False		
	Condition	Slightly Worn; Not Functioning	DIRTY,SLUGGISH	
	Pull	Select	6#	
Trigger	Altered	True	SEALANT MISSING	
	Sub-Assembly	M/700 Bolt Lock		
Non-Remington Components	Description		SCOPE BASE,RINGS	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9156&Type=... 9/26/2013

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9156&Type=... 9/26/2013

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

	ENE TOOKAP	PROVAL IN 21 DATS, WE WILL RETURN THE HEINIO	AO NECEIVED, PO	JUINOL DUL.			
Repair Number	S	erial Number / Description			Date Received:	09/16/2	2013
RE00321167		A6350621			Estimate Date:	09/17/2	
		Model 700 Center Fire Caliber: 30 -06			Date Printed:	09/26/2	
	-					****	
Customer:			Reti	urn To:			
PETE'S GUN				PETE'S GUNS			
ATTN: PETI				ATTN: PETE			
251 STATE				251 STATE ST			
CARTHAGE	., NY 13619	9 US		CARTHAGE,	NY 13619 US		
Please Circle One							
VISA MC	DISCOVI	ER Card No. PO Number:		Ex	p.Date		
Open Accour	nt: R	PO Number:					
Approval Signatu	ure:				_ Date:		
Daytime Phor	ne: ()_	Time	to Call:				
		e, please use the reverse side for your comment					_
		Pro	blems				
Reported			Found				
M123 - FORW	ARD TO PR	CODUCT SERVICE FOR INSPECTION			DUCT SERVICE FO	R INSPE	CTION
			M240 - BOL	T LOCK SAFE	TY MODIFICATION		
		Tachnicia	n Comments				
trigger assembly	dirty and set	screws altered replace trigger assembly check	over and test fir	e under holt loci	k program for \$20.00	+ shinnin	o
digger assembly	unity und sor	solows altered replace trigger assembly; offere	over and test in	o dilder beit ice.	k program 101 \$20.00	· Smppm	5
		ESTIMATE (note: C.O.D./Shipping and Han	dling Charges	ore NOT Inches	dod in this Quata		
Material	Туре	Description	Oty	Warranty	Qty Price	e Disc	Amount
1.14.61.14.	-76-		Needed		From Inv	2.50	
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLA	CK (OS) 1	Warranty	1 .00	0 0	.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REI	PAIR) 1	Billable	1 17.00	0	17.00
4000116	Service	GR-LABOR	20	Billable	20 1.00	0 0	20.00
4000119	Service	GR-TEST	1	Warranty	1 .00	0	.00
4000117	Berrice	GR-1E51	•	waitunty	1 .0.		.00
			^		_		
			O	1126112	5		
				.1 [
			0	raid	10011		
			<u> -</u>	1/26/13 Daid 6)(((#		
			,		•		
				df			
				O, 1			
					Sub Total:		37.00
					Est Sales Ta	v•	2.59
					Est Saies 12	л.	2.55
					Grand Total	l:	\$39.59

Remington

22"/7 D [9/7 6#

August 30, 2013

9156



Pete's Guns Attn: Pete 251 State St.

Carthage, NY 13619 Phone: 315-408-6675


Ref # 9156, Model 700, Serial # A6350621

Enclosed is a prepaid UPS shipping label to cover shipment of the firearm to our factory for examination.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co, LLC
Phone: 336-548-8686
Fax: 336-548-7872



BY:----



T.A. dinty + set schews Alt.

Nep. TAA, chick over+ toot

und BL? for 20+

Ċ

Remington Arms Company, LLC • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number:	Serial Number:			
Rem 700	A 635003			
Name: PETES GUUS	Date of Purchase:			
Address (no PO Boxes): 251 STATE ST				
CIET MAGE	State: 174 Zip: 13419			
Phone (Daytime): 315 408 4475	Fax:			
E-mail Address: gunquy 34 @ yahoo.com				
Please describe your problem:				
Som Times Mis fires and Then will go off when starting to court Gon from Shoulder				
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.				
OR IN THE SAME BOX WITH THE FEDERAL LAW. IF YOU FEEL YO SEND THEM IN A SEPARATE PARTY (WITH ZIP CODE), TELEPHONE AYOUR FIREARM.	E OR SPENT SHELLS IN YOUR FIREARM FIREARM. THIS IS A VIOLATION OF DU MUST SEND SPENT SHELLS PLEASE ACKAGE AND INCLUDE NAME, ADDRESS AND MODEL AND SERIAL NUMBER OF			
:: Record the serial number of your :: Pack your firearm for safety and t handling. Preferably, ship in a	firearm before sending it. to prevent further damage in shipping and			

firearm box. (Note: Original boxes may not be returned.)

:: Remove all accessories from your firearm to prevent loss or damage.
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not

during shipment, so you may elect to purchase insurance from your earrier.

use our UPS label

responsible for damage or loss

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700 ATTN: Product Service



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

SR00060565 Customer: PETE'S GUNS ATTN: PETE 251 STATE ST. CARTHAGE, NY 136	Serial Number / Description A6350621 Model 700 Center Fire Caliber: 3006	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357	Date of Request: Date Printed: US	09/03/2013 09/03/2013
Email:		Email:		
	item(s) will be evaluated by our repairman to determine if ntacted with an estimate before work is performed.	it is covered under our warranty poli	icy. If it is your firearm	will be repaired and
Reason For Return MI23 - FORWARD TO F	PRODUCT SERVICE FOR INSPECTION	· · · · · · · · · · · · · · · · · · ·		, , , , , , , , , , , , , , , , , , , ,
Service Request Section Product Service # 9156. dm	nf			
Parts And Service Details Material Type	Description	Qty Warranty Needed	Price	Disc Amount
THIS IS NOT AN INVOICE. To being sent based on the convers	his is a pre-estimate to repair, recondition, or replace the ite ation with our representative.	em(s)	Sub Total: Est Sales Tax: Grand Total:	.00 .00 \$.00

ARS LABEL REQUEST FORM

09/03/2013		Service Request #	SR00060565
1		WEIGHT PER PACKAGE:	10 LBS
fulcherdm		email address:	I WILL MAIL LABEL
	•		
	ì	fulcherdm	WEIGHT PER PACKAGE:

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

PETE'S GUNS ATTN: PETE 251 STATE ST. SR00060565 CARTHAGE, NY 13619 US Email:

RETURN ITEM TO:

ILN

Arms Services

4XX596 SEP 3, 2013 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969067521752 REF 1:SR00060565 REF 2: 1 OF 1

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: ECE PUB RATE CHKGS: COD 0.00 DGD 0.00 PR 0.00 DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 9.00 SVC T/P USD RS 0.50 SD 0.00 SP 0.00 PUB+HANDLING

ATTN: Product Service





