E johnrupert7@gmail.com

## Remington Arms Co., Inc. Product Service Legal Case #:9010

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 314224 6/25/2013 6/26/2013 6/26/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

ncident John Rupert 6901 Cheryl St. Anchorage AK 99518

H 907-349-1364

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern
S FSR Concern:1007 Fired on Safe Release

Unknown

C

Service Request# 54093 - Service Request Section: "wants safety modification states has fired when safety is taken off". df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/270 m/a 6489200 RU 11/1/1971

Date
Purchased Where Purchased Accessories Original
Owner

VF GRACE INC ANCHORAGE
ALASKA
U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Reimbursement Reimbursement Release Date Release Date Reimbursement Release Date Release Da

Per Ilion - Quote to repair under BLM

Repair/Replacement Repair/Replacement Cost Date

6/28/13: Per Ilion - Could not duplicate concern. TA dirty. Replace TA, clean & test under BLM - quote. df 7/1/13: Emailed quote to customer because he is in Alaska. df 7/17/13: Customer called Consumer Serv Dept, apprvd quote & paid. df

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9010&Type=... 7/22/2013

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		6/26/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		RU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		<del></del>
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS,SCRATCHES
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9010&Type=... 7/22/2013

### Fulcher, Dell Marie

From:

Fulcher, Dell Marie

Sent:

Monday, July 01, 2013 11:21 AM

To:

'johnrupert7@gmail.com'

Subject:

John Rupert - Quote to repair - Ref# 9010

Attachments:

mad2-sharp-front@remington.com\_20130701\_101748.pdf

#### Good morning,

Please see attached quote to repair.

Please contact us as soon as possible with approval and payment.

#### Sincerely,

Dell Marie Fulcher | Consumer Affairs Administrator Remington Arms Company, LLC

870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 | Phone: 336.548.8686 | Fax: 336.548.7872 or 336.548.7883 | Email:

<u>dell.fulcher@remington.com</u> Freedom Group Family of Companies: Remington | Marlin | Bushmaster Firearms | DPMS / Panther Arms | H&R | Barnes Bullets | Advanced Armament Corp | Mountain Khakis | Dakota Arms | Parker Gun | Para USA

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system.

## Fulcher, Dell Marie

From:

To: Sent:

Subject:

postmaster@remington.com johnrupert7@gmail.com Monday, July 01, 2013 11:21 AM Relayed: Message relayed (johnrupert7@gmail.com)

Delivery to these recipients or groups is complete, but no delivery notification was sent by the destination server:

johnrupert7@gmail.com

Subject:

## Quotation

# Remington Service PO Box 700

Estimating Report Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00314224	64	erial Number / Description 89200 odel 700 Center Fire Caliber: 270 WIN			Date Rece Estimate l Date Prin	Date:	06/25/2 06/26/2 06/28/2	013				
Customer: JOHN RUPEI 6901 CHERY ANCHORAG	'L STREET	8 US		rn To: JOHN RUPERT 6901 CHERYL S ANCHORAGE,		US						
Please Circle One	:	•										
VISA MC	DISCOVE	R Card No		Exp.	Date							
Open Account: RPO Number:												
Approval Signatu	re:				Date:							
			Cail:					,				
If you desire any change, please use the reverse side for your comments and mark this box.												
Reported Found M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION												
		Technician	Comments			•		50.74.79 as				
couls not duplicate concern trigger assembly dirty. replace trigger assembly, clean and test fire under bolt lock program for \$20.00 + shipping												
		STIMATE (note: C.O.D./Shipping and Hand		re NOT Include								
Material	Type	Description	Qty Needed	Warranty	Qty From Inv	Price	Disc	Amount				
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLAC	CK (OS) 1	Warranty	1	.00	0	.00				
4000114	Service	GR-SHIPPING & HANDLING (GUN REP.	AIR) 1	Billable	1	17.00	0	17.00				
4000116	Service	GR-LABOR	20	Billable	20	1.00	0	20.00				
4000119	Service	GR-TEST	1	Warranty	1	.00	0	.00				
					Sub T Est S	Γotal: ales Tax:	;	37.00 .00				
					Cunn	d Totali		\$37.00				

PO Box /00

05/31/2013

05/31/2013

Date of Request:

Date Printed:

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

72" Ruly; 45

Service Request Number

Serial Number / Description

SR00054093

6489200

Model 700270

\*Customer: JOHN RUPE

JOHN RUPERT 6901 CHERYL STREET ANCHORAGE, AK 99518 US 9010

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Emzil: johnrupert7@gmzil.com

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 · BOLT LOCK SAFETY MODIFICATION

Service Request Section

wants safety modification' states has fired when safety is taken off

Parts And Service Details

Material Type

Description

Qıv Needed Warranty

Price 1

Disc Amount

6489200

Model:

700

RE00314224

DECEIVE) N jun 2 8 2013

BY: -

could knot dup. Honcenus. TiA. Dirty, p.p. TPA, clear + Trost und. BLPfon 20T

THIS IS NOT AN INVOICE. This is a pre-estimate to repzir, recondition, or replace the

 $\mathcal{L}$ 

Sub Total: Est Sales Tax: .00

Grand Total:

\$.00







