Page 1 of 2 PrintDisplay

> Remington Arms Co., Inc. **Product Service** Legal Case #:9663

Case Information

RE# Date Opened(PS) Pre Lit Lit Obsolete **Date Opened Date Closed Incident Date** 332064 12/26/2013 12/11/2013 12/27/2013 12/7/2013

Customer Information

Type Business First Name Last Name Contact Street City State Zip Age Rt. 1 Box 207 - 1A Peterstown WV 24963 Juanita H 304-753-5765 Incident Sanders

Incident Information

FSR

Claims Codes Repair Est. Medical Treatment Medical Status

PI

PD Cause: 4015 Improper Maintenance

Concern: 1007 Fired on Safe Release

CF/BA

Unknown

N/A

6605026 BX 1/1/1973

S C

12/11/13: I received call from Juanita Sanders, he said that her son was using the rifle this past Saturday when it fired upon release of the safety. She said there were no injuries. jbi

Firearm Information

Remington

SKU Model/Ga. Serial Bbl. DOM Mfg. Type 700/22-250

REM Date Original

Where Purchased Accessories Purchased Owner

> SOUTHERN GUN DISTR MIAMI U

FLA

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Cash Release of Claims Settlement Release Date Reimbursement Date Date Settlement APV APV

Per Ilion. quote to repair **BLM**

> Repair/Replacement Repair/Replacement Cost Date

> > \$27

12/11/13: Sending ARS, letter, and SR paperwork. Box sent on SAP order 1574588. jbi 1/3/14: Per Ilion, "could not duplicate concern trigger assembly dirty and set screws altered replace trigger assembly, check over and test fire under bolt lock program for \$20.00 + shipping." jbi 1/10/14: I called and left message with quote. I received call from Juanita Sanders, she said that she will send in a check to my attention. jbi 1/13/14: I received letter approving quote and paid with check #1525. jbi

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9663&Type=... 1/13/2014

Page 2 of 2

PrintDisplay

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/27/2013
Examination	Product Type		RF
	Action Type		Α
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
	Description		24" 22-250 REM
	Date Code	7	BX
	Bore Plugged	False	
Barrel	Bulged	False	Ī
	Fired	False	7
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	-
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	=
	Ext/Eject Test	False	=
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
Dooking	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Overall	Fore End Condition	Select	_
	Condition	Slightly Worn; Functioning	\dashv
Receiver	Bulged	False	=
	Description	I alse	BOLT LOCK SAFETY
Safety		Like new; Functioning	BOLI LOCK SAFETT
	Function		
Sear	Lift	Select	
	Notch	Slightly Worn; Functioning	
n 1	Tests	Test Fired	False
Feeding Test		False	Dynasi caro
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
Trigger	Pull	Select	5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9663&Type=... 1/13/2014

i	Sin: here is a Check of 39.22 faw The Grun With the ref. no. 9663 Junto Sangue
'	Dus.
	here is a Check of 39.22 faw
	The Grun With the res. no. 9663
1112.11.11.11.11.11.11.11.11.11.11.11.11	Quanto Sandelle
	Janus Jangers
and the same of th	
Makangaga mininggalan man resorma. Ming 23 maa min 1922 m	
~ 1 +	
- and the state of	
and approximation in the last of the design	
	:
almost Petricina deport to the lateral and the second states of the seco	
alter alleganism sin and a	
1	

Remington

24" 12x1/23 5th

December 11, 2013

9663

Juanita Sanders Rt. 1 Box 207 – 1A Peterstown, WV 24963 Phone: 304-753-5675

Ref # 9663, Model 700, Serial # 6605026

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

_ I hope that this action will keep you a loyal Remington customer.

Sincerely, J.B. Irving Consumer Affairs Administrator Remington Arms Co, LLC / H&R Phone: 336-548-8684

Fax: 336-548-7872

DECEIVED 1 Jan 0 3 20,4

BY:____



could not dup, concern.
T.A. diphy, sticky + set screws
Alt. hip. T.A. chuekover +
rist und Bei fon 30 +

Q

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number	Serial Number / Description		Date of]	Request:	12/11/2013
SR00070826	6605026		Date	Printed:	12/11/2013
- .	Model 700	D = 41 = 44 = = 1			İ
Customer: JUANITA SANDERS		Destination: Arms Services			
RT I BOX 207 - IA		14 Hoefler Ave			
PETERSTOWN, WV	24963_US	Ilion, NY 13357	US -		٠
Email:		Email:			
Your request for service on the	e item(s) will be evaluated by our repairman to determin	e if it is covered under our warranty poli	icy. If it is	your firearm	will be repaired and
returned. If not, you will be or	entacted with an estimate before work is performed.				
Reason For Return		•			
	PRODUCT SERVICE FOR INSPECTION	•			
				·	
Service Request Section Product Service #9663. jbi					
Fraduct Service #9005. Joi					
Committee of the second of the second	The second control of	the second of th			
Parts And Service Details		O: 337			
Material Type	Description	Qty Warranty Needed		Price	Disc Amount
	•				
				ı	
		•			
	· .				
Ī					
					:
	/	e e	•		
	•				
	This is a pre-estimate to repair, recondition, or replace t	he item(s)		Total:	. 00
being sent based on the conve	rsation with our representative.		Est	Sales Tax	: .00
			Grs	ınd Total:	\$.00

ARS LABEL REQUEST FORM

DATE:	12/11/2013	Service Request #	SR00070826
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	irvingjb	email address:	I will mail
Business:		Remington Service PO Box 700 Madison NC 27025 0700	
		Madison, NC 27025-0700 www.Remington.com	

LABEL INFORMATION

	LABEL INFORMATION
MAIL LABEL TO:	JUANITA SANDERS RT BOX 207 - 1A PETERSTOWN, WV 24963 US SR00070826 Email:
RETURN ITEM TO:	ILN
	Arms Services



4XX596 DEC 11 SVC GNDCOM TRACKING# 1Z4XX5969 REF 1:SR00070826 REF 2:	ACT	WT 10.0 LE	URR USD 3S	1 OF
HANDLING CHARGE 0.0 SINGLE-PIECE PUB RA DV 0.00 DC 0.00	TE CHR COD DGD	0.00 0.00	RS SD	T/P USD 0.50 0.00
AH 0.00	PR	0.00	SP	0.00 10.34

ATTN: Product Service







