Remington Arms Co., Inc.

			oduct Service			
Case Information		Leg	al Case #:9377			
	Opened Date	Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit Obsolete
	~	0/31/2013	10/31/2013			
Customer Informa	ntion					
Type Busin	ness First Name	Last Name	Street	City State	Zip Age	e Contact
Reporter Schee		Scheels All Spo	800 Kirkwood Mall	Bismarck ND	58504	W 701-255- 7255
Incident	Carter	Medalen	311 1st St. N.E.	Rugby ND	58468	
Incident Informati	on					
Claims Codes Repair Est. Medical Treatm					eatment	Medical Status
	Cause: 4038 Could Not Duplicate Concern Concern: 1007 Fired on Safe Release Unknown					
	eels, "Customer sa	vs rifle will disc	harge when pushir	ng from "on" safe	to "off" safe	e." ibi
CONCERN:FSR Ammunition Infor	Where Purcha BILL HICKS & C mation - None De formation - None I	O LTD fined Defined	U			
		Remin	igton/700/CF/BA			D.: 0.1
Settlement	Release of Cla	ims Rele	ease Date Ro	imbursement S	Cash ettlement	Reim. Cash Date Date APV APV
Replace trigger, check over, and test at no charge						
	Repair/Replace Cost \$59		Replacement Date			
	Could not duplica up, Please do not u nctions. jbi					
Examination[Rem	ington/CF/BA]					

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9377&Type=... 11/6/2013

Page 2 of 2


Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/31/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 7MM RUM SS
	Date Code		CX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	***************************************
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	SEALANT MISSING
	Sub-Assembly	M/700 Non-Bolt Lock	


PrintDisplay

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9377&Type=... 11/6/2013









SCHEELS

Firearm Repair 802 Kirkwood Mall

Bismarck, ND 58504

Phone 701-255-7255 • Fax 701-258-0245

377 2365 2 ck

ATTENTION: The estimated time on repairs is 6 to 8 weeks depending on the availability of parts needed to repair your Firearm. DO NOT leave scopes, slings, cases etc... with the firearm, they may get lost or misplaced in the shuffle. RECEIVED BY JACOB Misum DATE ___ HOME PHONE OTHER PHONE 701-204-0011 **CUSTOMER NAME** ADDRESS STATE CITY MODEL MAKE 788 SERIAL NO. INSURANCE VALUE 5646 7713 **CUSTOMER SIGNATURE DESCRIPTION OF SERVICE TO BE DONE** FOR OFFICE USE ONLY SHIPPED BY **SENT TO:** COMPANY NAME ADDRESS CITY STATE DATE RETURNED ____ 20_ 20 CUSTOMER CONTACTED NA / LMOM / LMWP **AMOUNT DUE \$** CONTACTED REPAIR STATUS chick over + No ST

IES FIREARM

COST.

PINK - CUSTOMER COPY