PrintDisplay Page 1 of 2

Remington Arms Co., Inc.
Product Service
Legal Case #:8779

Legal Case #:8779 Case Information RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 306971 4/4/2013 4/5/2013 4/5/2013 Customer Information Type **Business** First Name Last Name Street City State Zip Contact Age William 408 MacArthur Rd Cold Brook NY 13324 H 315-826-5941 Incident Shurmer Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause:4038 Could Not Duplicate Concern Unknown S Fired when closing bolt Concern: 1008 Fired on Bolt Closing 4/9/13 Per note with rifle, shoots when bolt is closed.cm Firearm Information SKU Model/Ga. Serial Bbl. DOM Mfg. Type 700/270 WIN 134521 BM 1/1/1965 Remington CF/BA n/a **Date Purchased** Where Purchased Accessories Original Owner TWO PIECE TIP OFF BASE, SCOPE, SLING U CONCERN: FBC Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV Per Ilion, replace TPA, clean, test at BLSM program price Repair/Replacement Repair/Replacement Cost Date 4/9/2013 31.04 4/9/13 Per Ilion, could not duplicate concern. Trigger assm dirty and rusty. Replace TPA, clean, test at BLSM program price.cm Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner]	B.TRAVIS
	Exam Date]	4/5/2013
Examination	Product Type		RF
	Action Type]	Α
	Assigned To]	S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		BM
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	1

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8779&Type=Case

4/9/2013

PrintDisplay Page 2 of 2

İ	61 1	Tours we received	≒ !
	Shroud	Slightly Worn; Functioning	╡
Bolt	Face	Slightly Worn; Functioning	_
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	BOLT LOCK SAFETY N/A RUSTY False DIRTY,RUSTY 4.5# FACTORY SEALANT PRESANT
Safety	Description		BOLT LOCK SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	RUSTY
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
Triann	Pull	Select	4.5#
Trigger	Altered	False	FACTORY SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE TIP OFF BASE, SCOPE, SLING

22 BM1
1
:
1001
cenu. ty. Tiest
7.
, e 20, + 0 ج
:0 T
70%
7L
013
013
013
013
013

Security Copy - White

Arm Service Copy - Yellow

Customer Copy - Pink







