## Remington Arms Co., Inc. Product Service Legal Case #:9560

Case Infor	mation										
RE#	Date Opened	Date Opened(	PS)	Date Closed	Incide	nt Date	e Pre	Lit	Lit	Obsolete	
332066	12/26/2013	11/25/2013		12/27/2013	11/11	/2013					
Customer	Information										
Type E	Business First Nar	ne Last Name		Street	City	State	Zip A	Age	C	Contact	
Incident	Rick	Skane	32980	Two Creek Lane	Charlo	MT	59824		H 40	6-644-7767	
Incident In	formation										
Claims		Codes		Repair Est.	Med	ical Tr	reatment	t :	Medi	cal Status	
Pl											
PD	Cause:4015	Improper Maint	enance			Unkno					
S FSR	Concern:1007	Fired on Safe R	elease			UIKII	WII .				
С											
11/25/13: I received call from Rick Skane, he said that his gun fired on safety release. No injury. jbi											

Firearm Information						
Mfg.	Туре	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	26129	D6585441	LU	2/24/2000 2:07:43 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACUSPORT CORPORATION		N			
CONCERN: FSR						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

## Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV	
Per Ilion, replace trigger, check over, and test at 50% discount							
	Repair/Replacement Cost	Repair/Replacement Date					
12/1/12: Sourding ADS latter and SD nanowork Day cont on SAD order 1567802 this 1/2/14: Der Ilian "action and							

12/1/13: Sending ARS, letter, and SR paperwork. Box sent on SAP order 1567892. jbi 1/3/14: Per Ilion, "action and trigger assembly very dirty, sticky, and rusty causing parts to bind and work sluggish. Can offer to replace trigger assmebly, check over, and test fire at 1/2 cost." jbi 1/13/14: I called and left message requesting a call back. I received call from Rick Skane, he said that the check is in the mail. jbi

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9560&Type=... 1/13/2014

.

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date	Ī	12/27/2013
	Product Type	1	RF
	Action Type	1	A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
	Description		22" 3006 SPRG
	Date Code	1	LU
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	RUSTY BOLT HEAD
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Not Functioning	ACTION DIRTY, RUSTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	]
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD SAFETY

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9560&Type=... 1/13/2014

.

Safety	Function	Like new; Functioning	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	VERY DIRTY,STICKY,RUSTY WILL FOLLOW DOWN
Trigger	Pull	Select	10+#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

Quota	ation			Estimating Report					
Parts and R	lepairs: P:/F:		3				Page	e: 1	
		E IN EXCHANGE FOR REP							
PLEASE APPR	OVE BY SIGNIN RECEIVE YOUR	S IS AN ESTIMATE TO REPAIR, R G BELOW AND RETURNING TO R APPROVAL IN 21 DAYS, WE WI	THE ABOVE ADDRESS. REP .L RETURN THE ITEM(S) AS I	AIR TO TAKE API Received, post	PROXIMATELY AGE DUE.	(6) WEEKS AF	TER RECEIP	t of Appr	OVAL.
		warranties concerning lega are advised to check their l						iws or	
c	Customer:					tem Return	Tai		
L	RICK SI	CANE			,	RICK SK			
		WO CREEK LANE					VO CREEI	K LANE	
	CHARL	0, MT 59824 US				CHARLO	D, MT 598	324 US	
Please Circle	One:		<u>, ,</u>						
		OVER Card No.			Ex	p.Date			
Open Acc	count: R	OVER Card No	PO Number:						
Approval Sig	mature:					_ Date:	<b></b>		
		_)							
Repair Num		Serial Number / Descript				Date Re	coived.	12/26/20	13
RE00332066		D6585441				Estimat		01/08/20	
		Model 700 Center Fire C				Date Pri	inted:	1/8/2014	
<b>Reported</b> R014 - FO	RWARD TO	PRODUCT SERVICE FOR		ns ound 014 - FORWA	RD TO PRO	DÙCT SERV	VICE FOR	INSPECT	TION
			Technician Co	mmante					
		y very dirty, sticky and rusty est fire at 1/2 cost.			can offer to re	eplace trigge	r	·····	
		ESTIMATE (note: C.O.I	D./Shipping and Handlin						
Material	Туре	Description		Qty Needed	Warranty	Qty From Inv	Price	-	Amount
F305570B 4000114	Part Scrvice	X-MARK PRO 700 TRIC GR-SHIPPING & HAND		) 1	Billable Billable	1 1	97.00 17.00	50 0	48.50 17.00
4000119	Service	GR-TEST	LING (GON KEI AIK)	1	Billable	1	23.00	50	11.50

•



22

December 1, 2013

Rick Skane 32980 Two Creek Lane Charlo, MT 59824 Phone: 406-644-7767

Ref # 9560, Model 700, Serial #D6585441

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

I-hope that this action will keep you a loyal Remington customer.

Sincerely, J.B. Irving Consumer Affairs Administrator Remington Arms Co, LLC / H&R Phone: 336-548-8684 Fax: 336-548-7872

Serval D6585441 Model:

JAN 0 3 2014

ВҮ:

Act. + T. H. weny dinty, sticky findy causing pants to bind + work slug, CAN of the to Mp. T.A. check over MUST at 1/2 LOST.

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

## Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00069266 Customer: RICK SKANE 32980 TWO CREEK I CHARLO, MT 59824 Email: Your request for service on th returned. If not, you will be c	D6585441 Model 700DM RIFLE ANE	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 Email: etermine if it is covered under our warranty po ied.		12/01/2013 12/01/2013 will be repaired and
Service Request Section	PRODUCT SERVICE FOR INSPECTION			
Product Service #9560. jb	این او به ایران ایران ایران ایران ایرا	a da anti-anti-anti-anti-anti-anti-anti-anti-	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	••••• • • • • • • • • • • • • • • • •
Parts And Service Detail Material Type	S Description	Qty Warranty Needed	Price	Disc Amount
		•		
	• •			
	This is a pre-estimate to repair, recondition, or re	values the item(s)	Sub Total:	. 00
	This is a pre-estimate to repair, recondition, or restion with our representative.	prace uic (icili(s)	Sub Total: Est Sales Tax: Grand Total:	

## ARS LABEL REQUEST FORM

DATE: 2201/2013		Service Request#	SR60069256
QUANTIFY:		WEIGHT PER PACKA	GE: 191.88
REQUESTED BY: PRINKIN		ernail address;	
Business	Remington Servia PO Ben 200 Madaun, NC 27 www.Remington	623-6766	
	LABEL IN	IFORMATION	
MAIL LABEL TO:	RICK SEANE 32980 TWO CRI CHARLO, MT SR00069256 Emsil	UK LANE S9834 US	
RETURN ITEM TO:	ILN Arms Services		
	े संस् इड्डा सिंहम् स्टब्स्	Kings IJaxx596995614	
ATTN: Product Service		000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000	CCS: GVC 37, PLOD 8.000 PS 8.50 6.000 SD 8.000 6.399 SP 6.000 РОСИНСКО, ТИС 14.29









