PrintDisplay Page 1 of 2

Remington Arms Co., Inc.
Product Service
Legal Case #:8572

				Lega	al Case #:8572						
Case Infor	mation										
		Opened Date Open 2013 2/5/20				Incident Date			Pre Lit	Lit	Obsolete
Customer	Information										
Туре	Business	First Name	Last Name	S	treet	City	State	Zip	Age	Cor	tact
		Steppe	2401 Windy Ridge Rd		Cogan PA 17728		_		2@live.com		
Incident In	formation		••			Ū					•
Claims				•	Codes		Repair Est.		Medical Treatment		Medical Status
PΙ											
PD Cause:4			006 Altered	r							
	from safe to	fire the firing pin		Compo	Components 1007 Fired on Safe Release				Unknown		
drops			Concern	:1007 Filed C	in Sale Release						
	nata an SI) comotimos o	aina from cafa t	a fire the fir	ina nin drans G	aaina	off on i	te over e	200		
		C, sometimes, g	ong from safe i	o tire, the fir	ing pin drops. G	un gonig	011 011 1	15 OWII.			
Firearm In	formation										
	1fg.		Туре		odel/Ga.	SKU			Serial	Вы.	DOM
Remington			F/BA		2506 REM	25789			E6287987	PQ	6/28/1996
Date Purchased		Where Purchased			cessories	Original Owner		wner			
CONCERN: FSR		WALTER	WALTER CRAIG INC		PIECE BASE	Ŭ					
	ducts Inform	ion - None Defi ation - None D									
				Remin	gton/700/CF/BA	1					
Settlement Release of Cl		clease of Claim	ms Release Date		Reimb	urseme	nt	Cash Ro tlement	im. Dat APV	te Cash Dat APV	
	PA, clean at 2 normal cos										
17.	z normar co.		pair/Replaceme Cost	ent Repair	r/Replacement						
2/21/13 Pe	er Ilion, trigg	ger assm set scr		gger not retur	ning under sear.	Replace	TPA, c	lean and	l test at 1/2 no	ormal co	st.cm
Examination	on[Remingt	on/CF/BA]							~		
	Part	Sut	Sub-Part		Code		Comment				
		Examiner				B.TRA	VIS				
1		Exam Date	e			2/5/201	3				
Examinati	ion	Product Ty				RF					
		Action Ty				Α					
		Assigned '	Го			S.NICE	IOLS		-		
Cause		4006		ltered Adjust omponents	ments or]					
		Descriptio	n			24" 250	6 REM				
		Date Code				PQ					

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8572&Type=Case

False

False

False

Bore Plugged

Fired while Obstructed

Bulged

Fired

Barrel

2/21/2013

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	<u> </u>
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning]
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning]
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		STANDARD SAFETY
Sarety	Function	Like new; Functioning	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	lesis	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING UNDER SEAR WILL FOLLOW DOWN
Trigger	Pull	Select	1.5#
	Altered	True	SET SCREWS ALTERED SEALANT CHANGED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700.F:336-548-7801

www.Remington.com

This document is a sammary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

2411

Service Request Number

Serial Number / Description

SR00043033

E62\$79\$7

Model 700 RIFLE

Customer: JOE STEPPE

2401 WINDY RIDGE RD.

COGAN, PA 17728 US

Date of Request: Date Printed:

01242013 01/24/2013

Arms Services 14 Hoeiler Ave Hon. NY 13357 US

Email: joesher62@live.com

"Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

SOMETIMES, GOING FROM SAFE TO FIRE, THE FIRING PIN DROPS. GUN GOING OFF ON ITS OWN

Parts And Service Details

Material

Type

Description

Warranty

Price

Disc Amount

E6287987

Model:



BY:

T.A. set screws Alt. Thig. NOT Returne CEAR. Mp. TDA, CLOAN + Test AT 1/2 NOR M (105)

THIS IS NOT AN INVOICE. This is a pra-astimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00





