

|            |                |                    |             |                           |                                           |
|------------|----------------|--------------------|-------------|---------------------------|-------------------------------------------|
|            |                | REM PRT3006B 165GR | 40          |                           |                                           |
|            |                | REM R30063 150GR   | 40          |                           |                                           |
|            |                | <b>TOTAL</b>       | <b>200</b>  | <b>NO PROBLEMS NOTED.</b> |                                           |
| <b>GUN</b> | <b>SERIAL#</b> | <b>AMMO</b>        | <b>RDS.</b> | <b>M.F.</b>               | <b>BOLT OVERRIDE STEM LOW FOLLOW DOWN</b> |
| A-10       | XC 1125        | REM R30065 180GR   | 40          |                           |                                           |
|            |                | REM R30067 220GR   | 40          |                           |                                           |
|            |                | REM L30062 150GR   | 40          |                           |                                           |
|            |                | REM PRT3006B 165GR | 40          |                           |                                           |
|            |                | REM R30063 150GR   | 40          |                           |                                           |
|            |                | <b>TOTAL</b>       | <b>200</b>  | <b>NO PROBLEMS NOTED.</b> |                                           |
| <b>GUN</b> | <b>SERIAL#</b> | <b>AMMO</b>        | <b>RDS.</b> | <b>M.F.</b>               | <b>BOLT OVERRIDE STEM LOW FOLLOW DOWN</b> |
| A-11       | XC 1126        | REM R30065 180GR   | 40          |                           |                                           |
|            |                | REM R30067 220GR   | 40          |                           |                                           |
|            |                | REM L30062 150GR   | 40          |                           |                                           |
|            |                | REM PRT3006B 165GR | 40          |                           |                                           |
|            |                | REM R30063 150GR   | 40          |                           |                                           |
|            |                | <b>TOTAL</b>       | <b>200</b>  | <b>NO PROBLEMS NOTED.</b> |                                           |
| <b>GUN</b> | <b>SERIAL#</b> | <b>AMMO</b>        | <b>RDS.</b> | <b>M.F.</b>               | <b>BOLT OVERRIDE STEM LOW FOLLOW DOWN</b> |
| A-12       | XC 1127        | REM R30065 180GR   | 40          |                           |                                           |
|            |                | REM R30067 220GR   | 40          |                           |                                           |
|            |                | REM L30062 150GR   | 40          |                           |                                           |
|            |                | REM PRT3006B 165GR | 40          |                           |                                           |
|            |                | REM R30063 150GR   | 40          |                           |                                           |
|            |                | <b>TOTAL</b>       | <b>200</b>  | <b>NO PROBLEMS NOTED.</b> |                                           |
| <b>GUN</b> | <b>SERIAL#</b> | <b>AMMO</b>        | <b>RDS.</b> | <b>M.F.</b>               | <b>BOLT OVERRIDE STEM LOW FOLLOW DOWN</b> |
| A-13       | XC 1128        | REM R30065 180GR   | 40          |                           | 3                                         |
|            |                | REM R30067 220GR   | 40          | 2                         | REPLACED RECEIVER INSERT ASSY.            |
|            |                | REM L30062 150GR   | 40          |                           | SEAR STICKING, CAUSING THE                |
|            |                | REM PRT3006B 165GR | 40          |                           | FOLLOW DOWNS.                             |
|            |                | REM R30063 150GR   | 40          |                           |                                           |

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0000633

ETE00003532