

			TOTAL	200	2	3	
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE	STEM LOW	FOLLOW DOWN
A-14	XC 1129	REM R30065 180GR	40				
		REM R30067 220GR	40				
		REM L30062 150GR	40				RD# 81 TRIGGER PIVOT PIN CAME OUT, REPLACED
		REM PRT3006B 165GR	40				
		REM R30063 150GR	40				RD# 178 AND 190 MAG BOX CAME APART
			TOTAL	200			
GUN	SERIAL#	AMMO	RDS.	M.F.	BOLT OVERRIDE	STEM LOW	FOLLOW DOWN
A-15	XC 1130	REM R30065 180GR	40				
		REM R30067 220GR	40				
		REM L30062 150GR	40				
		REM PRT3006B 165GR	40				
		REM R30063 150GR	40				
			TOTAL	200			NO PROBLEMS NOTED.
MALFUNCTIONS ALL GUNS ALL AMMO TYPES							
		AMMO	RDS.	M.F.	BOLT OVERRIDE	STEM LOW	FOLLOW DOWN
		REM R30065 180GR	600		2		3
		REM R30067 220GR	600				
		REM L30062 150GR	600				
		REM PRT3006B 165GR	600				
		REM R30063 150GR	600				
			TOTAL	3000	2		3

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.060007068

ETE00003533