

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

File Number: 9553 Arms Service number: 9719521

Last Name: BILL EDWARD GUN SHOP First Name:

Street: 102 13TH ST SE City: MENOMONIE

State: WI Zip: 54751 Home Ph:

Work Ph: 715 232 0556 Product Type: F A T O

Type Concern: E P P D P S C Concern Code: 1007

Concern: FIRED ON SAFE RELEASE

Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS

Assigned To: KASR Classification: UNJ UNJ UNC UND J

Settlement Detail: REPAIR SPCL PRICE Settlement Amount: \$0.00

Date Opened Rem: 9/12/97 Date Opened by P/S: 9/12/97 Caliber: 300WIN

Date of Incident: 9/1/97 Date Closed: 9/12/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: 6532020 Date Code: AW Date Mfgd: 3/1/72

HAMAC: 700 Litigation: ☐ PreLitigation: ☐ Obsolete: ☐

Custody: Comments:

Time of Modification: 3:21:17 PM Date of Modification: 9/12/97

Form View

FLTR

CAPS

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-15621INITIAL
JJM

ATTN JACK KAST

DATE RECEIVED
09/10/97DATE OPENED
09/12/97DATE CODE
AW 3-72SERIAL NUMBER
6532020

NEW SERIAL NUMBER

MODEL AND GRADE

700 300WIN

MAG/BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

BILL EDWARDS GUN SHOP
102 13TH STREET SE
MENOMONIE

WI 54751

SHIP TO:

BILL EDWARDS GUN SHOP
102 13TH STREET SE
MENOMONIE

WI

54751

CUST NO: 167497 C.G.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

4200
total

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D1	E4	F4
WOOD		C1		D2	E5	F5
METAL		C2		D3		

MAIN FAULT

All three trigger adjusting screws have been altered outside of the factory - not recommended and inside of trigger is gummed up with old solidified oil. Exchange tag 4354 at a special price strictly as a gesture of goodwill.

PARTS

COMMENTS

Trigger pull measured 3 to 3 1/4 lbs as reqd.

Bolt stop sticks as reqd.

See owners manual for proper care and maintenance.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 9/96



Bill Edwards'

Gun Shop
And
Hay River Game Farm

(715) 232-0558

102 13th Street SE
Menomonie, WI 54751

9-4-97

ATT: JACK KAST

Re: Rem 708 BDL
300 WM
653202

This rifle has discharged on two occasions, 1984 when safety was taken off and blowing a hole in Dr. L. Phillips kitchen floor (checking on feeding and two weeks ago Caribou hunting in Alaska while trying to clear the rifle for the night it fired while in the tent when the safety was taken off.

Please see what is wrong.

Thank you,
Bill Edwards

Serving The Sportsman Since 1968