

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

File Number: 9022 Arms Service number: 9700905

Last Name: BOBS GUN EXCHANGE First Name:

Street: PO BOX 627 City: GOSHEN

State: NY Zip: 10924 Home Ph:

Work Ph: Product Type: F A T O

Type Concern: 5 M P D P S C Concern Code: 1007

Concern: FIRED ON SAFE RELEASE

Cause Code: 4015 Cause: IMPROPER MAINTENANCE

Assigned To: SANITA Classification: UNJ UNJ UNC UND J

Settlement Detail: REPAIR AT SPEC PRICE Settlement Amount: \$0.00

Date Opened Rem: 1/13/97 Date Opened by P/S: 1/21/97 Caliber: 30.06

Date of Incident: Date Closed: 1/21/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: 86274925 Date Code: RB Date Mfgd: 11/1/91

RAMAC: 700 Litigation: ☐ PreLitigation: ☐ Obsolete: ☐

Custody: Comments:

Time of Modification: 6:39:50 AM Date of Modification: 1/24/97

Has this model been designated as obsolete? FLTR CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-00905

INITIAL CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/02/97

01/13/97

RB 11-B1

B6274925

700 30-06

ADL

ACCESSORIES

W/STUDS

1/ aperture

FROM:

SHIP TO:

BOBS GUN EXCHANGE
PO BOX 827
RT 17M
GOSHEN

NY 10924

BOBS GUN EXCHANGE
PO BOX 827
RT 17M
GOSHENNY
10924

ACCOUNT NUMBER

ACCOUNT NUMBER NIC

CUST NO: 004096 IL-10N

06310 3

WRITE ☐

FROM DATE

ESTIMATED

VIA

1/29/97

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

25.00

8.00

33.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Sent to product service

Upon receipt we could not duplicate the reported problem, but did find that the bolt stop release & cam safety cam are wearing slightly from being covered with a heavy sticky substance. Customer needs cleaning. R/LB M/L 1/98

COMMENTS

Replace the cam safety trigger cam
& clean the action at 1/2 the normal
cleaning.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OF ICE COPY

RD6925 REV. 11/96

ANCE

N. 10924

essories

DATE

1/12/97

1997

ANCE DUE ON ALL DEPOSITS
DAYS FROM DATE SHOWN
No Cash Refunds

W # B6274925

Customer complains of discharge
when moving safe.

Thank:

Bob

DEPOSIT HELD FOR 30 DAYS ONLY.

SF-28