

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

File Number: 270 Arms Service number: 8706780

Last Name: EPLLY First Name: STEPHEN

Street: 1709 PLEASANTVILLE DR City: GLEN BURNIE

State: MD Zip: 21061 Home Ph:

Work Ph: Product Type: F F A T O

Type Concern: S PI PD P S C Concern Code: 1007

Concern: FIRED ON SAFE RELEASE

Cause Code: 4016 Cause: IMPROPER MAINTENANCE

Assigned To: KAST Classification: UNJ UNJ UNC UND J

Settlement Detail: REPAIR SPCL PRICE Settlement Amount: \$0.00

Date Opened Rem: 3/20/97 Date Opened by P/S: 3/20/97 Caliber: 308

Date of Incident: Date Closed: 3/20/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: T6211126 Date Code: XP Date Mfgd: 12/1/95

RAMAC: 700 Litigation: PreLitigation: Obsolete:

Custody: Comments: rusty trigger

Time of Modification: 2:04:26 PM Date of Modification: 3/20/97

Form View FLTR NUM

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 97-04780

INITIAL CUSTOMER ORDER NO.

JJM

ATTN JACK KAST CAMO TAPE ON METAL

DATE RECEIVED

03/19/97

DATE OPENED

03/20/97

DATE CODE

XP 12-95

SERIAL NUMBER

T6211126

NEW SERIAL NUMBER

MODEL AND GRADE

700 308

SS/DM/SNY

ACCESSORIES

FROM:

EPLEY, STEPHEN  
1709 PLEASANTVILLE DR  
GLEN BURNIE

MD 21061

SHIP TO:

EPLEY, STEPHEN  
1709 PLEASANTVILLE DR  
GLEN BURNIE MD  
21061

CUST NO: 162179 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☐ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

REC. ASSY.

B5

WOOD

METAL

D2

MAIN FAULT

Same. Trigger stays in pulled position due to rust on trig. trigger housing and trigger pivot pin. Exchange trig at a special price strictly as a gesture of good will.

PARTS

COMMENTS

Krig 354

Also: breech bolt and firing pin threads rusty

See owners manual for proper care &amp; maintenance

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 6/96

PS 34549

STEPHEN EPLEY  
1709 PLEASANTVILLE DRIVE.  
GLEN BURNIE MD. 21061

PRODUCT SERVICE  
REMMINGTON ARMS  
14 HOELFER AVE  
ILION, NY. 13357  
ATTN: JACK CAST


## WARNING

DEAR MR JACK CAST;

THIS PRODUCT IS THE FIRST OF ITS KIND THAT I HAVE EVER COME ACROSS, ONE THAT CAN CAUSE INSTEAD DEATH IF NO ONES KNOWS THEIR FIRE ARM SAFETY. WHEN I LOADED UP THE CLIP AND INSERTED IT INTO THE RIFLE, SET ON THE TARGET CLOSING THE BOLT IN THE READY TO FIRE POSITION. THE FIRING PIN KEPT GOING FORWARD, LUCKILY IT DID NOT DISCHARGE AFTER THIS HAPPENED I CLEAR THE AREA OF PEOPLE PLACING THE RIFLE ON SAFETY THE FIRING PIN STAYED IN THE FIRE POSITION. WITH ME FINGER OFF THE TRIGGER AND THE RIFLE FIRMLY AGAINST MY SHOULDER I PUSHED THE SAFETY FOR WHICH CAUSED THE RIFLE TO FIRE.

WHAT I WOULD LIKE OUT OF THIS NOT TO CHANGE THE UPPER RECEIVER AND BARREL BECAUSE OF ITS ACCURACY, BUT WOULD LIKE TO RECEIVE 2 EXTRA CLIP FOR MY INCONVENIENCE

THANK YOU;

  
STEPHEN A. EPLEY