

File Number: 9669		Arms Service number: 9717920	
Last Name: HAMMOND		First Name: JACON	
Street: 1707 N KUTCH		City: FLAGSTAFF	
State: AZ	Zip: 86001	Home Ph: 520 774 7641	
Work Ph:	Product Type: F	F A T O	
Type Concern: S	PI PD P S C	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4005	Cause: ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To: KAST	Classification: UNJ UNJ UNC UND J		
Settlement Detail: REPAIR N/C	Settlement Amount: \$0.00		
Date Opened Rem: 10/20/97	Date Opened by P/S: 10/20/97	Caliber: 30-06	
Date of Incident:	Date Closed: 10/20/97	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: 377882	Date Code: ER	Date Mfgd: 10/1/68
RAMAC: 700	Litigation: ☐	PreLitigation: ☐	Obsolete: ☐
Custody:	Comments:		
Time of Modification: 2:19:59 PM		Date of Modification: 10/20/97	

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-17920

INITIAL CUSTOMER ORDER NO.

ATTN JACK KAST

JJM
DATE RECEIVED 10/17/97 DATE OPENED 10/20/97 DATE CODE ER 10-68 SERIAL NUMBER 377882 NEW SERIAL NUMBER MODEL AND GRADE 700 30-06 ADL
ACCESSORIES SCOPE BASE W/STUDS

FROM:

SHIP TO:

HAMMOND, JASON
1707 N KUTCH
FLAGSTAFF

AZ 86001

HAMMOND, JASON
1707 N KUTCH
FLAGSTAFF

AZ
86001

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 175047 C.O.D.

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Charge good with.

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

*if gun sits for awhile it will
fire when bolt is closed*

*Unable to duplicate customer concern as rec'd.
Replace trig. assy. at n/c to restore customer
confidence in the rifle*

PARTS

COMMENTS

trig pull 3 1/2 to 4 LBS

*Sear engagement screw had been
adjusted at some time outside
of the factory BUT was in spec.
as rec'd.*

Rust on firing pin tip

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 7 97

PS 34610

Jack Cast,

After the gun sits for a while when you run the Bolt in, it will fire the first time you do this. It was first ~~happened~~ Happened when it fired on my Dad he did not know the Reason till several years later when I noticed it do this During a Elk Hunt. We have taken it to gunsmiths and they have worked on the trigger but it still did the same thing. We had talked to a guy from Remington several years ago and he said something about the Bolt not being cleaned properly. I also talked to a guy the other day who said it was the Lugs or Spring in the Bolt. If you have Any Question Call me.

Jason Hammond

1707 N. Kutch

Flystaff, AZ 86001

(520) 774-7641