

File Number:	9881	Serial Number:	9721001
Last Name:	HIGGINS	First Name:	SCOTT
Street:	13517 SUNNY LNE	City:	LAKESIDE
State:	CA	Zip:	92040
Work Ph:		Home Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	
Concern Code:	1007		
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ
			UNJ UNC UND J
Settlement Detail:	REPAIR AT SPECIAL PRICE		Settlement Amount:
			\$0.00
Date Opened Repair:	12/4/97	Date Opened by:	
Date of Incident:		Date Closed:	12/10/97
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	REM
Model:	700	Serial:	272968
		Date Code:	CP
RAMAC:	700	Date Mfgd:	4/1/67
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Obsolete:	<input type="checkbox"/>		
Custody:		Comments:	RIFLE POORLY MAINTAINED
Time of Modification:	10:26:16 AM	Date of Modification:	12/11/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER

R 97-21001

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/02/97

12/04/97

CP 4-67

272968

700 30-06

ADL

ACCESSORIES

SCOPE BASE

L/STUDS

FROM:

SHIP TO:

HIGGINS SCOTT
13517 SUNNY LANE
LAKESIDE

CA 92040

HIGGINS SCOTT
13517 SUNNY LANE
LAKESIDECA
92040

CUST NO: 178082 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

28.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

36.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Upon receipt the 1967 manufactured rifle was in operation. The trigger when pulled would not retract. Examination revealed heavy coat of dirt & oil on & inside the trigger housing assembly. The trigger & connector were seized together, more than normal. Gun was required to remove these components. We noted that all 3 trigger adjustment screws have been set.

#26345

1007

4006 &

4015

JD Walsh

Repair the connector trigger screw & clean the action at 1/2 the normal pressure.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
JM					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD9925 REV 97

Greetings Remington Arms Co.

11/13/97

I recently was on a hunting trip in northeast Wyoming. While we were on a freinds ranch the day before hunting opened, we decided to sight in our rifles. I put a shell into my Remington 30-06, rested on the bench, sighted the target and flipped off the safety. I was extremely surprised when the rifle fired. There was no harm to anyone but it was a nervous experience. The stock on the same rifle has developed a split near the trigger. Whether these problems are related I do not know.

I own other Remington products and have had good performance with all but this 30-06. I am very disappointed with this particular rifle, and it is dangerous.

I am sending my rifle to you, in hope that you can remedy these problems. Please notify me after assessing this rifle.

RE: Remington M-700, 30-06
serial # 272968

Thank You
Scott Higgins
13517 Sunny Lane
Lakeside, Ca. 92040
(619) 390-4898