

File Number:	9664	Arms Service number:	9715378	
Last Name:	JENKINS	First Name:	CUSTOM AMMN SPL	
Street:	5746 E PIMA	City:	TUCSON	
State:	AZ	Zip:	85712	
Work Ph:	520 881 0266	Product Type:	F F A T O	
Type Concern:	S	PI PD P S O	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE			
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE	
Assigned To:	KAST	Classification:	UNJ UNJ UNG UND J	
Settlement Detail:	REPAIR SPCL PRICE	Settlement Amount:	50.00	
Date Opened Rm:	9/10/97	Date Opened by P/S:	10/20/97	
Date of Incident:		Date Closed:	10/20/97	
Date to Analysis:		Date from Analysis:		
Model:	700	Serial:	5578746	
RAMAC:	700	Litigation:		
Custody:		Comments:	also altered adjustments	
Time of Modification:	6:04:54 AM	Date of Modification:	10/20/97	

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-15378

INITIAL CUSTOMER ORDER NO.

JJM 107701

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

09/08/97

09/10/97

DW 7-72

6578746

700

30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

FROM:

SHIP TO:

JENSENS CUSTOM AMMN SPLY
5146 E PIMA
BRANT SABAU
TUCSON

AZ 85712

JENSENS CUSTOM AMMN SPLY
5146 E PIMA
BRANT SABAU
TUCSON

AZ
85712

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

44.00

Total

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		<i>Fires when bolt is closed</i>				F1
BOLT ASSY.		B3				E2
BARREL ASSY.		<i>and when safety is taken off</i>				F3
REC. ASSY.		B5		D2		F4
WOOD				D3	E5	F5
METAL						

MAIN FAULT

When trigger was pulled as rec'd. it was very stiff and sluggish and stuck in the pulled position then fired when safe was released. Took trigger assy apart and found components were gummed up with schalac like substance.

Exchange trigger assy at a spot price strictly as a gesture of good will.

PARTS

trigger assy.

COMMENTS

*Sear engagement screw altered outside of factory. Not Recommended
Rounds pull screw altered - not Recommended
Bolt stop sticks as rec'd.*

See owners manual for proper care and maintenance.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

FACTORY RETURN / REPAIR

DATE 8-13-97

REFERENCE # 107701

This number must appear on all correspondence, invoices, shipping papers and packages.

RETURNED TO:

Remington
1-315-895-3200

RETURNED FROM:

Jensen's
65146 E Tama St
Tucson, AZ 85712
(520) 881-0266
Attn: Christy

ITEM DESCRIPTION (Include Make, Model & Product Code)	Serial #	Caliber	Condition	Qty.
<u>Remington 700</u>	<u>6578746</u>	<u>30-06</u>	<u>fair</u>	<u>1</u>

REASON FOR RETURN

fires when bolt is closed and when
safety is pushed off.

ACTION REQUESTED

Warranty Requested

*** **NOTE:** If there is a charge involved on a repair, please provide us with an estimate of charges for our approval BEFORE completion of work. Thank you for your cooperation.

RETURN AUTHORIZATION # _____

VENDOR PERSONNEL AUTHORIZING RETURN _____

RESTOCK FEE YES _____ NO _____ % _____

VENDOR INVOICE # AND DATE _____

AUTHORIZED BY Christy Schacht LOCATION OF PRODUCT _____